



**Planning & Research  
Problem Statement**

**Maintenance**

---

**Problem Title :** Investigate causes of premature longitudinal cracking on some new DJCP

**Problem Statement:**

Investigate causes of premature longitudinal cracking on some new DJCP. Determine the loss of utility caused by cracking. Two locations where a longitudinal crack appeared shortly after construction are:

SH-99 North of Seminole

US-77 North of Norman.

**Contact:**

Oklahoma Department of Transportation  
Planning & Research Division  
200 N. E. 21<sup>st</sup> Street, Room 3-A7  
Oklahoma City, Oklahoma 73105-3204  
Phone (405) 521-2671, (405) 521-6917 fax  
E-Mail [spr@odot.org](mailto:spr@odot.org)