

2009 ODOT Standard Specifications for Highway Construction
Errata

Section Number	Description of Errata	Date Posted
101.03	Subsection 101.03, end of Table 101:1 (pg. 5) Replace “Stated” with “States” in the acronym for USFWS.	8-25-10
109.04	Subsection 109.04.B.(3) Revise the equation for hourly rental rate to: $H = (M \times R \times A) / 176 + O$	2-16-12
307.04	Subsection 307.04.F.(2).(c), 2 nd sentence Delete the words “(tested in a dry condition).”	1-27-11
307.04	Subsection 307.04.F.(2).(c), Table 307:1 Revise the table heading to “Table 307:2, Soil-Additive Mixture Gradation.”	1-27-11
317.02	Subsection 317.02 Reference for Curing Agents should be 701.07.	8-25-10
317.02	Subsection 317.02, last paragraph Insert the words “degree of survivability” after the words “Class 1.”	1-27-11
317.04	Subsection 317.04.C, 2 nd line (pg. 180) Replace “rising” with “falling.”	8-25-10
317.06	Subsection 317.06, last sentence Delete the words “and asphalt cement.”	1-27-11
318.04	Subsection 318.04, 3 rd paragraph, 1 st sentence (pg. 182) Delete the word “unconfined.”	1-27-11
319.04	Subsection 319.04.C.(4), 1 st sentence Replace “maximum density” with “density (unit weight).”	1-27-11
325.04	Subsection 325.04.B, 2 nd paragraph, 2 nd sentence The misspelled word “role” should be spelled “roll.”	10-13-11
326.02	Subsection 326.02, last sentence Replace “AASHTO M288 for Class 1 geotextiles” with “Subsection 712.04.”	1-27-11
414.04	Subsection 414.06, last sentence Revise the reference to read 414.04.R, “Acceptance of Pavement.”	12-8-11
501.04	Subsection 501.04.B.(1), 3 rd paragraph, last sentence “standard” density should be “maximum” density.	1-27-11
505.02	Subsection 505.02, 5 th item in list of materials Delete the words “Special Provisions.”	1-27-11

2009 ODOT Standard Specifications for Highway Construction
Errata

Section Number	Description of Errata	Date Posted
509.04	Subsection 509.04.A, 1 st paragraph (pg. 346) Change the reference “414.04.E, ‘Setting Forms’” to “414.04.B, ‘Handling, Measuring, and Batching Materials’.”	8-25-10
509.04	Subsection 509.04.F.(4), 1 st paragraph, 2 nd sentence The misspelled word “hite” should be “white.”	1-27-11
513.06	Subsection 513.06, 3 rd pay item (pg. 401) Change the pay item (C) <i>Class C Bridge Deck</i> to (C) <i>Class C Bridge Deck Repair</i> .	8-25-10
513.06	Subsection 513.06, 1 st line (pg. 402) Add “concrete material” to the list of items covered by the <i>Bridge Deck Repair</i> pay items.	8-25-10
514.02	Subsection 514.02.E, last sentence (pg. 403) The words “sheet piling” should not be repeated in this sentence.	3-20-12
514.06	Subsection 514.06, 4 th paragraph Delete	2-16-12
514.06	Subsection 514.06, 7 th paragraph Delete	2-16-12
516.04	Subsection 516.04.C.7.a, last sentence (pg. 433) Revise reference to read 516.04.C.7.g	8-25-10
516.04	Subsection 516.04.C.7.c, 1 st sentence Revise “24 hrs” to read “3 to 7 days”	8-25-10
517.05	Subsection 517.05, 2 nd paragraph (pg. 459) Replace “prestressing” with “post-tensioning”.	8-25-10
622.02	Subsection 622.02, 1 st sentence (pg. 520) Change the reference “732.02, ‘Guide Posts’” to “732.04, ‘Pipe Railing’”.	8-25-10
701.01	Subsection 701.01.C, 13 th bullet (pg. 553) Delete “C, ‘High Range Water Reducer (HRWR) Concrete Mixture’”.	8-25-10
701.17	Subsection 701.17 The misspelled word “PROPORATIONING” should be spelled “PROPORTIONING”.	8-25-10
703.01	Subsection 703.01, Table 703:1 (pg. 584) The data in the table is misaligned.	8-25-10

2009 ODOT Standard Specifications for Highway Construction
Errata

Section Number	Description of Errata	Date Posted
707.01	Subsection 707.01.B, Table 707:1 The Micro Surfacing Limit for the Sand Equivalent property should read $\geq 65\%$.	1-27-11
708.02	Top of page (pg. 601) Revise header from "708.03" to "708.02".	8-25-10
719.04	Subsection 719.04.A (pg. 634) Revise Type II to Type III	8-19-11
726.02	Subsection 726.02, Table 726:3 (pg. 652) Delete footnote d.	8-25-10
880.02	Subsection 880.02.B.(6) Revise MUTCD reference from Section 6F-5 to Section 6F-7.	1-24-12
Index	Index pg. 808, "Separator Fabric for Bases" Section No. should be 325, 712	9-1-11