

2009 ODOT Standard Specifications for Highway Construction
Errata

Section Number	Description of Errata	Date Posted
101.03	End of Table 101:1 (pg. 5) Replace “Stated” with “States” in the acronym for USFWS.	8-25-10
317.02	Subsection 317.02 Reference for Curing Agents should be 701.07	8-25-10
317.04	Subsection 317.04.C, 2 nd line (pg. 180) Replace “rising” with “falling”.	8-25-10
509.04	Subsection 509.04.A; 1 st paragraph (pg. 346) Change the reference “414.04.E, ‘Setting Forms’” to “414.04.B, ‘Handling, Measuring, and Batching Materials’”.	8-25-10
513.06	3 rd pay item (pg. 401) Change the pay item (C) <i>Class C Bridge Deck</i> to (C) <i>Class C Bridge Deck Repair</i> .	8-25-10
513.06	First line (pg. 402) Add “concrete material” to the list of items covered by the <i>Bridge Deck Repair</i> pay items.	8-25-10
516.04	516.04.C.7.a; Last line (pg. 433) Revise reference to read 516.04.C.7.g	8-25-10
516.04	516.04.C.7.c; 1 st sentence Revise “24 hrs” to read “3 to 7 days”	8-25-10
517.05	Subsection 517.05; Second paragraph (pg. 459) Replace “prestressing” with “post-tensioning”.	8-25-10
622.02	Subsection 622.02; First sentence (pg. 520) Change the reference “732.02, ‘Guide Posts’” to “732.04, ‘Pipe Railing’”.	8-25-10
701.01	Thirteenth bullet (pg. 553) Delete “C, ‘High Range Water Reducer (HRWR) Concrete Mixture’”.	8-25-10
701.17	Title (pg. 576) “PROPORATIONING” should be “PROPORTIONING”.	8-25-10
703.01	Table 703:1 (pg. 584) Realigned the table.	8-25-10

708.02	Top of page (pg. 601) Revise header from "708.03" to "708.02".	8-25-10
726.02	Table 726:3 (pg. 652) Deleted footnote d.	8-25-10