

July 12, 2011

Certifications

All certifications will be found in the calibration and verification books relevant to that lab. Exceptions are the following: Soils equipment and balances; those will be in ta brown folder setting next to the soils verification books. Certifications for equipment used in the calibration or verification of equipment in multiple labs, such as thermometers, will be found in a folder marked Certifications in the top drawer of the file cabinet nearest the door to QA/IA's office.

"The mission of the Oklahoma Department of Transportation is to provide a safe, economical, and effective transportation network for the people, commerce and communities of Oklahoma."