

**Lab Equipment Calibration**  
(Spare Equipment)

Frequency (Mnths.)	Count of Equip.
0	8
1	1
3	2
6	10
12	556
24	13
36	1

Total Equipment: 591

Lab Id	Lab Name
91	Central Bituminous Liquid Lab

**Elastic Recovery**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
111	N\A	none assigned	Humboldt	H-1030	Quality Assurance	Check	Needs Procedure	View	<a href="#">View</a>		12	

**Mold**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	8/29/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
112	S-8	S8ER	Humboldt	H-1030	Quality Assurance	Check	Needs Procedure	View	<a href="#">View</a>		12	

**Mold**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	8/29/2019	Lai, Binh 0057	

## Flash Test

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
140	10	10CO	Koehler	14000	Quality Assurance	Check	SOP-124	View	View		12	

### Cleveland Open Cup

Action Status	Date	Technician	Certificate
Spare Equipment	2/8/2021	McCullough, Donald 0004	
Check	2/7/2020	Lai, Binh 0057	<a href="#">View</a>
Check	2/11/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1753	17	17CO	Tanaka	ACO-02-001	Quality Assurance	Check	SOP-124	View	View		12	

### Cleveland Open Cup

Action Status	Date	Technician	Certificate
Spare Equipment	2/8/2021	McCullough, Donald 0004	
Check	2/7/2020	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
139	1	1CO	Koehler	14000	Quality Assurance	Check	SOP-124	View	View		12	

### Cleveland Open Cup

Action Status	Date	Technician	Certificate
Spare Equipment	5/12/2022	McCullough, Donald 0004	
Check	2/28/2022	Lai, Binh 0057	<a href="#">View</a>
Check	2/22/2021	Lai, Binh 0057	<a href="#">View</a>
Check	2/7/2020	Lai, Binh 0057	<a href="#">View</a>
Check	2/11/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3562	21	2139004	Anton Paar	107267	Quality Assurance	Check	SOP-124	View	View		12	

### Cleveland Open Cup

Action Status	Date	Technician	Certificate
Spare Equipment	5/13/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
147	2	2CO	Koehler	14000	Quality Assurance	Check	SOP-124	View	View		12	

Cleveland Open Cup

Action Status	Date	Technician	Certificate
Spare Equipment	5/12/2022	McCullough, Donald 0004	
Check	2/28/2022	Lai, Binh 0057	<a href="#">View</a>
Check	2/22/2021	Lai, Binh 0057	<a href="#">View</a>
Check	2/7/2020	Lai, Binh 0057	<a href="#">View</a>
Check	2/11/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
148	3	3CO	Koehler	14000	Quality Assurance	Check	SOP-124	View	View		12	

Cleveland Open Cup

Action Status	Date	Technician	Certificate
Spare Equipment	5/12/2022	McCullough, Donald 0004	
Check	2/28/2022	Lai, Binh 0057	<a href="#">View</a>
Check	2/22/2021	Lai, Binh 0057	<a href="#">View</a>
Check	2/7/2020	Lai, Binh 0057	<a href="#">View</a>
Check	2/11/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
537	3	3FL	Koehler	K15610	Quality Assurance	Check	SOP-128	View	View		12	

Tag Filling Level Gauge

Action Status	Date	Technician	Certificate
Spare Equipment	1/12/2021	McCullough, Donald 0004	
Check	3/23/2020	Lai, Binh 0057	<a href="#">View</a>
Check	3/20/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
541	3	3TC	Koehler	K15520	Quality Assurance	Check	SOP-128	View	View		12	

**Tag Glass Test Cup**

Action Status	Date	Technician	Certificate
Spare Equipment	1/11/2021	McCullough, Donald 0004	
Check	3/23/2020	Lai, Binh 0057	<a href="#">View</a>
Check	3/20/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
144	4	4CO	Koehler	14000	Quality Assurance	Check	SOP-124	View	View		12	

**Cleveland Open Cup**

Action Status	Date	Technician	Certificate
Spare Equipment	5/12/2022	McCullough, Donald 0004	
Check	2/28/2022	Lai, Binh 0057	<a href="#">View</a>
Check	2/22/2021	Lai, Binh 0057	<a href="#">View</a>
Check	2/7/2020	Lai, Binh 0057	<a href="#">View</a>
Check	2/11/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
146	5	5CO	Koehler	14000	Quality Assurance	Check	SOP-124	View	View		12	

**Cleveland Open Cup**

Action Status	Date	Technician	Certificate
Spare Equipment	5/12/2022	McCullough, Donald 0004	
Check	2/28/2022	Lai, Binh 0057	<a href="#">View</a>
Check	2/22/2021	Lai, Binh 0057	<a href="#">View</a>
Check	2/7/2020	Lai, Binh 0057	<a href="#">View</a>
Check	2/11/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
141	6	6CO	Koehler	14000	Quality Assurance	Check	SOP-124	View	View		12	

**Cleveland Open Cup**

Action Status	Date	Technician	Certificate
Spare Equipment	7/25/2023	McCullough, Donald 0004	
Check	2/16/2023	Lai, Binh 0057	<a href="#">View</a>
Check	2/28/2022	Lai, Binh 0057	<a href="#">View</a>
Check	2/22/2021	Lai, Binh 0057	<a href="#">View</a>
Check	2/7/2020	Lai, Binh 0057	<a href="#">View</a>
Check	2/11/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1748	6	6TC	Fisher Scientific	K15520	Quality Assurance	Check	SOP-128	View	View		12	

**Tag Glass Test Cup**

Action Status	Date	Technician	Certificate
Spare Equipment	1/19/2021	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
142	7	7CO	Koehler	14000	Quality Assurance	Check	SOP-124	View	View		12	

**Cleveland Open Cup**

Action Status	Date	Technician	Certificate
Spare Equipment	5/12/2022	McCullough, Donald 0004	
Check	2/28/2022	Lai, Binh 0057	<a href="#">View</a>
Check	2/22/2021	Lai, Binh 0057	<a href="#">View</a>
Check	2/7/2020	Lai, Binh 0057	<a href="#">View</a>
Check	2/11/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
145	8	8CO	Tanaka	ACO-02-001	Quality Assurance	Check	SOP-124	View	View		12	

**Cleveland Open Cup**

Action Status	Date	Technician	Certificate
Spare Equipment	2/8/2021	McCullough, Donald 0004	
Check	2/7/2020	Lai, Binh 0057	<a href="#">View</a>
Check	2/11/2019	Lai, Binh 0057	<a href="#">View</a>

**Float Test**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
33	2	2FC	Humboldt	H-1410	Quality Assurance	Check	SOP-138	View	View		12	

**Aluminum Float**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	10/1/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
52	4	4BC	Humboldt	H-1420	Quality Assurance	Check	SOP-138	View			12	

**Brass Collar**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	2/25/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
49	unassigned	unassigned-a	Humboldt	H-1420	Quality Assurance	Check	SOP-138	View	View		12	

**Brass Collar**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	10/1/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
50	unassigned	unassigned-b	Humboldt	H-1420	Quality Assurance	Check	SOP-138	View	View		12	

**Brass Collar**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	10/1/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
51	unassigned	unassigned-c	Humboldt	H-1420	Quality Assurance	Check	SOP-138	View	View		12	

**Brass Collar**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	10/1/2019	Lai, Binh 0057	

**Ovens and Furnaces**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3727	LO0457	23703397	IPC Global	81-PV2610/	Quality Assurance	Check	SOP-187	View	View		12	

**Oven - Vacuum Degassing**

Action Status	Date	Technician	Certificate
Spare Equipment	10/9/2023	McCullough, Donald 0004	
Check	7/14/2023	Lai, Binh 0057	View
Standardize	7/14/2023	Lai, Binh 0057	View

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
749	LO0340	99071	Prentex	9900E1G	Quality Assurance	Check	SOP-187	View	View	View	12	

**Oven - Degassing**

Action Status	Date	Technician	Certificate
Spare Equipment	10/9/2023	McCullough, Donald 0004	
Check	2/23/2023	Lai, Binh 0057	<a href="#">View</a>
Standardize	2/23/2023	Lai, Binh 0057	<a href="#">View</a>
Check	2/22/2022	Lai, Binh 0057	<a href="#">View</a>
Standardize	2/22/2022	Lai, Binh 0057	<a href="#">View</a>
Standardize	2/24/2021	Lai, Binh 0057	<a href="#">View</a>
Check	2/24/2021	Lai, Binh 0057	<a href="#">View</a>
Standardize	2/20/2020	Lai, Binh 0057	<a href="#">View</a>
Check	2/20/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/8/2019	Lai, Binh 0057	
Standardize	8/8/2019	Lai, Binh 0057	

**Penetration Test**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
756	A-2148	A-2148	Humboldt	H-1280	Quality Assurance	Check	SOP-131	View	View		12	

**Needles**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	6/6/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
757	A-2192	A-2192	Humboldt	H-1280	Quality Assurance	Check	SOP-131	View	View		12	

**Needles**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	6/6/2019	Lai, Binh 0057	



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
753	A-2204	A-2204	Humboldt	H-1280	Quality Assurance	Check	SOP-131	View	View		12	

Needles

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	6/6/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3538	B-2351	B-2351	Humboldt	H-1300	Quality Assurance	Check	SOP-131	View			12	

Needles

Action Status	Date	Technician	Certificate
Spare Equipment	4/15/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3536	FL0509	FL0509	Humboldt	H-1240	Quality Assurance	Standardize	SOP-131	View			12	

Apparatus

Action Status	Date	Technician	Certificate
Spare Equipment	4/14/2022	McCullough, Donald 0004	

**Pressurized Aging Vessel**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1747	LAE0713	2042-01	Cooper	CRT-PAV1	Quality Assurance	Calibrate	OS100		View		6	

Pressurized Aging Vessel

Action Status	Date	Technician	Certificate
Spare Equipment	1/11/2021	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
774	LAT0225	M95-0910	ATS	M950910331	ATS	Calibrate	OS100		View		6	

**Pressurized Aging Vessel**

Action Status	Date	Technician	Certificate
Calibrate	10/5/2022	External Agency	View
Standardize	10/5/2022	External Agency	View
Standardize	4/7/2022	External Agency	View
Calibrate	4/7/2022	External Agency	View
In Service	4/4/2022	McCullough, Donald 0004	
Spare Equipment	3/21/2022	McCullough, Donald 0004	
Standardize	10/6/2021	External Agency	View
Calibrate	10/6/2021	External Agency	View

**Rheometer**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
45	FL2355	11-7142	ATS	WG. 4-8897	ATS	Calibrate	OS100		View		6	

**Bending Beam Rheometer**

Action Status	Date	Technician	Certificate
Spare Equipment	2/14/2024	McCullough, Donald 0004	
Calibrate	1/11/2024	External Agency	View
Calibrate	5/11/2023	External Agency	View
Calibrate	10/6/2022	Lai, Binh 0057	View
Calibrate	4/7/2022	External Agency	View
Calibrate	10/5/2021	External Agency	View

**Ring and Ball**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
802	2	2R	Humboldt	H-1575	Quality Assurance	Check	SOP-127	View	View		12	

**Shouldered Ring and Ball**

Action Status	Date	Technician	Certificate
Check	4/10/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1295	5	5RA	Humboldt	H-1569	Quality Assurance	Check	SOP-127	View	View		12	

Ring Holder

Action Status                      Date                      Technician                      Certificate

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1296	6	6RA	Humboldt	H-1569	Quality Assurance	Check	SOP-127	View	View		12	

Ring Holder

Action Status                      Date                      Technician                      Certificate

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
805	8	8R	Humboldt	H-1575	Quality Assurance	Check	SOP-127	View	View		12	

Shouldered Ring and Ball

Action Status                      Date                      Technician                      Certificate  
 Check                      4/10/2019                      Lai, Binh                      0057

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3593	FL2483	B070MY-BB-0005	Humboldt	H-157		Check	/materials/C97001	View	View		12	

Automatic Digital Apparatus

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      8/26/2022                      McCullough, Donald                      0004

## Sieves

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2102	3	11345066	Gilson	V3SF #50	Calibration Solutions	Check	OS100		View		12	

3" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	1/7/2021	McCullough, Donald 0004	
Check	9/7/2020	Lai, Binh 0057	View
Check	9/5/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2103	5	11345067	Gilson	V3SF #50	Calibration Solutions	Check	OS100		View		12	

3" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	1/7/2021	McCullough, Donald 0004	
Check	9/7/2020	Lai, Binh 0057	View
Check	9/5/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2105	7	11345069	Gilson	V3SF #50	Calibration Solutions	Check	OS100		View		12	

3" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	1/7/2021	McCullough, Donald 0004	
Check	9/7/2020	Lai, Binh 0057	View
Check	9/5/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2318	1	153-20	W.S. Tyler	WS-1296	Calibration Solutions	Check	OS100		View		12	

3" (#20)

Action Status	Date	Technician	Certificate
Spare Equipment	1/7/2021	McCullough, Donald 0004	
Check	9/7/2020	Lai, Binh 0057	View
Check	9/5/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2320	1	1S3-50	Gilson	V3SF #50	Calibration Solutions	Check	OS100		<a href="#">View</a>		12	

3" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	1/7/2021	McCullough, Donald 0004	
Check	9/7/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/5/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2392	2	2S3-20	W.S. Tyler	WS-1296	Calibration Solutions	Check	OS100		<a href="#">View</a>		12	

3" (#20)

Action Status	Date	Technician	Certificate
Spare Equipment	1/7/2021	McCullough, Donald 0004	
Check	9/7/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/5/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2394	2	2S3-50	Gilson	V3SF #50	Calibration Solutions	Check	OS100		<a href="#">View</a>		12	

3" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	1/7/2021	McCullough, Donald 0004	
Check	9/7/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/5/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3583	3	3S3-50	Gilson	V3SF #50	Calibration Solutions	Check	OS100		<a href="#">View</a>		12	

3" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	8/17/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2466	4	4S3-50	Gilson	V3SF #50	Calibration Solutions	Check	OS100		View		12	

3" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	1/7/2021	McCullough, Donald 0004	
Check	9/7/2020	Lai, Binh 0057	View
Check	9/5/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2537	6	6S3-50	Gilson	V3SF #50	Calibration Solutions	Check	OS100		View		12	

3" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	1/7/2021	McCullough, Donald 0004	
Check	9/7/2020	Lai, Binh 0057	View
Check	9/5/2019	Lai, Binh 0057	

### Specific Gravity

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3525	07214953	07214953	Fisherbrand	11-603N	Quality Assurance	Check	SOP-000	View			36	

Hydrometer

Action Status	Date	Technician	Certificate
Spare Equipment	3/7/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1732	167843	167843	ERTCO	API Petro	Quality Assurance	Check	SOP-175	View			24	

Hydrometer

Action Status	Date	Technician	Certificate
Spare Equipment	12/7/2020	McCullough, Donald 0004	

## Thermometers

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
607	07000028	07000028	Omega	HH804U	Calibration Solutions	Standardize	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

### Digital Display/Green

Action Status	Date	Technician	Certificate
Spare Equipment	7/26/2022	McCullough, Donald 0004	
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/26/2020	External Agency	<a href="#">View</a>
Standardize	10/17/2019	External Agency	<a href="#">View</a>
Standardize	4/5/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1220	07000028	07000028-12	Omega	UNKNOWN	Calibration Solutions	Standardize	OS100		<a href="#">View</a>		12	

### Probe#20/Green/12"

Action Status	Date	Technician	Certificate
Spare Equipment	7/26/2022	McCullough, Donald 0004	
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/26/2020	External Agency	<a href="#">View</a>
Standardize	10/17/2019	External Agency	<a href="#">View</a>
Standardize	4/5/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1224	07000028	07000028-6	Omega	HH804U	Calibration Solutions	Standardize	OS100		<a href="#">View</a>		12	

### Probe#21/Green/6"

Action Status	Date	Technician	Certificate
Spare Equipment	7/26/2022	McCullough, Donald 0004	
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/26/2020	External Agency	<a href="#">View</a>
Standardize	10/17/2019	External Agency	<a href="#">View</a>
Standardize	4/5/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1267	1779	1779	Ludwig Schneider	ASTM47F-86	oss Precision Measureme	Standardize	OS100		View		12	

Liquid in Glass

Action Status	Date	Technician	Certificate
Spare Equipment	11/4/2021	McCullough, Donald 0004	
Standardize	5/10/2021	External Agency	<a href="#">View</a>
Standardize	5/12/2020	External Agency	<a href="#">View</a>
Standardize	10/18/2019	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1260	198057	198057-18	Digi-Sense	Type K	Calibration Solutions	Standardize	OS100		View		12	

Probe#18/Thermocouple

Action Status	Date	Technician	Certificate
Spare Equipment	1/3/2022	McCullough, Donald 0004	
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/26/2020	External Agency	<a href="#">View</a>
Standardize	10/17/2019	External Agency	<a href="#">View</a>
Standardize	4/5/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3682	3060	3060	Ertco	ASTM 17F	Calibration Solutions	Standardize	OS100				12	

Saybolt Viscosity

Action Status	Date	Technician	Certificate
Spare Equipment	9/1/2021	McCullough, Donald 0004	



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1228	307	307	Ertco	ASTM133C01	oss Precision Measureme	Standardize	OS100		View		12	

Liquid in Glass

Action Status	Date	Technician	Certificate
Spare Equipment	5/9/2023	McCullough, Donald 0004	
In Service	6/13/2022	McCullough, Donald 0004	
Standardize	6/10/2022	External Agency	View
Discarded	12/27/2019	Groom, Michael D. 2629	
Standardize	5/16/2018	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1231	6538	6538	Ertco	ASTM 63F	Calibration Solutions	Standardize	OS100		View		12	

Liquid in Glass

Action Status	Date	Technician	Certificate
Spare Equipment	10/2/2023	McCullough, Donald 0004	
Standardize	8/18/2022	External Agency	View
Standardize	8/27/2021	External Agency	View
Standardize	8/26/2020	External Agency	View
Standardize	10/17/2019	External Agency	View
Standardize	5/9/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1232	6550	6550	Ertco	ASTM 63F	Calibration Solutions	Standardize	OS100		View		12	

Liquid in Glass

Action Status	Date	Technician	Certificate
Spare Equipment	10/2/2023	McCullough, Donald 0004	
Standardize	8/18/2022	External Agency	View
Standardize	8/27/2021	External Agency	View
Standardize	8/26/2020	External Agency	View
Standardize	10/17/2019	External Agency	View
Standardize	5/9/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1276	80312537	80312537-16	Control Company	Type K	Calibration Solutions	Standardize	OS100		View		12	

Probe#16/Thermocouple

Action Status	Date	Technician	Certificate
Spare Equipment	11/22/2021	McCullough, Donald 0004	
Standardize	8/26/2020	External Agency	View
Standardize	10/17/2019	External Agency	View

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3349	LV0046-Probe	RTD00057	Tempco	E19 01	Calibration Solutions	Standardize	OS100		View		12	

Saybolt Viscometer

Action Status	Date	Technician	Certificate
Spare Equipment	9/1/2021	McCullough, Donald 0004	

### Timing Devices

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
529	51154561	51154561	Fisher Scientific	14-648-3	Quality Assurance	Standardize	SOP-114	View	View		12	

Stopwatch

Action Status	Date	Technician	Certificate
Spare Equipment	2/29/2024	McCullough, Donald 0004	
Standardize	2/12/2024	Lai, Binh 0057	View
Standardize	2/10/2023	Lai, Binh 0057	View
Standardize	2/9/2022	Lai, Binh 0057	View
Standardize	2/8/2021	McCullough, Donald 0004	View
Standardize	2/10/2020	Lai, Binh 0057	View
Standardize	2/6/2019	Lai, Binh 0057	

## Viscometer

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3527	LV0055	1214-A1022	Cannon	TE-DPV	Quality Assurance	Standardize	SOP-137	View	View	View	6	

Rotational Paddle Viscometer

Action Status                      Date                      Technician                      Certificate

Lab Id    Lab Name  
92        Central Chemical Lab

## Autoclave

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
41	ACM-1	ACM-1	Humboldt	H-3253-S	Quality Assurance	Check	SOP-156	View	View		12	

Mold

Action Status                      Date                      Technician                      Certificate

Spare Equipment                      8/24/2023                      McCullough, Donald    0004

Check                                      3/10/2023                      Lai, Binh    0057                      [View](#)

Check                                      3/10/2022                      Lai, Binh    0057                      [View](#)

Check                                      3/10/2021                      Lai, Binh    0057                      [View](#)

Check                                      6/8/2020                      Lai, Binh    0057                      [View](#)

Check                                      6/5/2019                      Lai, Binh    0057                      [View](#)

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
42	ACM-2	ACM-2	Humboldt	H-3253-S	Quality Assurance	Check	SOP-156	View	View		12	

Mold

Action Status                      Date                      Technician                      Certificate

Spare Equipment                      8/24/2023                      McCullough, Donald    0004

Check                                      3/10/2023                      Lai, Binh    0057                      [View](#)

Check                                      3/10/2022                      Lai, Binh    0057                      [View](#)

Check                                      3/10/2021                      Lai, Binh    0057                      [View](#)

Check                                      6/8/2020                      Lai, Binh    0057                      [View](#)

Check                                      6/5/2019                      Lai, Binh    0057                      [View](#)

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
37	ACM-3	ACM-3	Humboldt	H-3253-S	Quality Assurance	Check	SOP-156	View	View		12	

**Mold**

Action Status	Date	Technician	Certificate
Spare Equipment	8/24/2023	McCullough, Donald 0004	
Check	3/10/2023	Lai, Binh 0057	<a href="#">View</a>
Check	3/10/2022	Lai, Binh 0057	<a href="#">View</a>
Check	3/10/2021	Lai, Binh 0057	<a href="#">View</a>
Check	6/8/2020	Lai, Binh 0057	<a href="#">View</a>
Check	6/5/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
38	ACM-4	ACM-4	Humboldt	H-3253-S	Quality Assurance	Check	SOP-156	View	View		12	

**Mold**

Action Status	Date	Technician	Certificate
Spare Equipment	8/24/2023	McCullough, Donald 0004	
Check	3/10/2023	Lai, Binh 0057	<a href="#">View</a>
Check	3/10/2022	Lai, Binh 0057	<a href="#">View</a>
Check	3/10/2021	Lai, Binh 0057	<a href="#">View</a>
Check	6/8/2020	Lai, Binh 0057	<a href="#">View</a>
Check	6/5/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1293	FL2184	FL2184	Humboldt	H-3250	Quality Assurance	Check	Needs Procedure	View	View		12	

**Length Comparator (Digital Indicator 10272055)**

Action Status	Date	Technician	Certificate
Spare Equipment	8/24/2023	McCullough, Donald 0004	
Check	3/15/2023	Lai, Binh 0057	<a href="#">View</a>
Check	3/17/2022	Lai, Binh 0057	<a href="#">View</a>
Check	3/15/2021	Lai, Binh 0057	<a href="#">View</a>
Check	8/17/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/14/2019	Lai, Binh 0057	<a href="#">View</a>
Check	8/21/2018	External Agency	<a href="#">View</a>

## Cement Testing

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3753	N-005	N-005	Gilson	WT-1	Quality Assurance	Check	SOP-143	View			6	

325 Sieve Spray Nozzle

Action Status	Date	Technician	Certificate
Spare Equipment	2/1/2024	McCullough, Donald	0004

## Graduated Cylinders

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
663	K-4	K-4011	Kimax	20024-150	Quality Assurance	Standardize	SOP-151	View	View		12	

Glass

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D.	2629
Standardize	7/22/2019	Lai, Binh	0057

## Mixer

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3524	LS0092	31-1229-744	Hobart Corpotation	N-50A	Quality Assurance		SOP-153	View	View			

5 Quart Mixer

Action Status	Date	Technician	Certificate
Spare Equipment	7/12/2021	McCullough, Donald	0004

## Scales

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
449	FL2327	B008014005	Mettler	HB43-S	Calibration Solutions	Calibrate	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

### Moisture Analyzer

Action Status	Date	Technician	Certificate
Spare Equipment	1/27/2022	McCullough, Donald 0004	
Calibrate	8/30/2021	External Agency	<a href="#">View</a>
Calibrate	8/24/2020	External Agency	<a href="#">View</a>
Calibrate	3/24/2020	External Agency	<a href="#">View</a>
Calibrate	10/17/2019	External Agency	<a href="#">View</a>
Calibrate	10/8/2018	External Agency	<a href="#">View</a>

## Tamping Tools

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3550	CT 28	CT 28	Humboldt	H-2860	Quality Assurance	Check	SOP-144	<a href="#">View</a>			12	

### Cement Tamper (Rubber)

Action Status	Date	Technician	Certificate
Spare Equipment	5/2/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3551	CT 29	CT 29	Humboldt	H-2860	Quality Assurance	Check	SOP-144	<a href="#">View</a>			12	

### Cement Tamper (Rubber)

Action Status	Date	Technician	Certificate
Spare Equipment	5/2/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3552	CT 30	CT 30	Humboldt	H-2860	Quality Assurance	Check	SOP-144	<a href="#">View</a>			12	

### Cement Tamper (Rubber)

Action Status	Date	Technician	Certificate
Spare Equipment	5/2/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3553	CT 31	CT 31	Humboldt	H-2860	Quality Assurance	Check	SOP-144	View			12	

Cement Tamper (Rubber)

Action Status	Date	Technician	Certificate
Spare Equipment	5/2/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3554	CT 32	CT 32	Humboldt	H-2860	Quality Assurance	Check	SOP-144	View			12	

Cement Tamper (Rubber)

Action Status	Date	Technician	Certificate
Spare Equipment	5/2/2022	McCullough, Donald 0004	

## Thermometers

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1197	080046	080046-12	Omega	HH804U	Calibration Solutions	Standardize	OS100		View		12	

Probe#13/Green/Red 12"

Action Status	Date	Technician	Certificate
Spare Equipment	7/26/2022	McCullough, Donald 0004	
Check	8/27/2021	External Agency	View
Standardize	8/27/2021	External Agency	View
In Service	9/10/2020	McCullough, Donald 0004	
Out of Service for Repair	9/1/2020	McCullough, Donald 0004	
Standardize	10/17/2019	External Agency	View
Check	10/17/2019	External Agency	View
Standardize	3/20/2019	External Agency	View
Check	3/20/2019	External Agency	View

## Thermometers - High Humidity Area

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1188	LAT0252-B82597	B82597	Fluke	2626-S	Quality Assurance	Check	SOP-106	View	View	View	6	

### Sensor/Thermo-Hygrometers

Action Status	Date	Technician	Certificate
Check	1/29/2018	Lai, Binh 0057	<a href="#">View</a>
Check	1/29/2018	External Agency	<a href="#">View</a>

## Unit Weight

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
47	AIR-1	AIR-1	Humboldt	H-3840	Quality Assurance	Calibrate	SOP-146	View	View		24	

### Brass Air Content Measure, 400mL

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Calibrate	6/28/2019	Lai, Binh 0057	<a href="#">View</a>

Lab Id	Lab Name
93	Central Bituminous Mixture Lab

## Bath

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
591	WB-1	3E1750063	Polyscienc	MX-CA11B	Quality Assurance	Standardize	SOP-115	View	View	View	12	

### Bath Heater

Action Status	Date	Technician	Certificate
In Service	10/16/2020	McCullough, Donald 0004	
Standardize	10/12/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	10/15/2019	Lai, Binh 0057	
Standardize	10/2/2018	Lai, Binh 0057	



## Freezers

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
656	FL2366	0121286501130130	Isotemp	13-986-148	Quality Assurance	Check	SOP-103	View	View		12	

### Freezer

Action Status	Date	Technician	Certificate
Out of Service for Repair	4/16/2019	McCullough, Donald 0004	
Check	4/12/2019	Lai, Binh 0057	

## Gyratory

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
409	100803	100803	Pine	AFLSC01	Pine	Calibrate	OS100		View		12	

### Rapid Angle Measurement Kit (cal tube)

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Calibrate	7/18/2018	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
411	134	134	Pine	AFLS1	Pine	Calibrate	OS100		View		12	

### Rapid Angle Measurement Kit (device)

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Calibrate	7/18/2018	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
458	1963	1963	Pine	AFGBM15	Quality Assurance	Check	SOP-120	View	View		12	

### Mold and Plate

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	4/9/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
263	203	203	Troxler	DAV2-HMS	Troxler	Calibrate	OS100		View		12	

**Gyratory DAV II HMS**

Action Status	Date	Technician	Certificate
Spare Equipment	6/3/2020	McCullough, Donald 0004	
Calibrate	8/21/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1692	FL2123	5038	Pine	AFGB1A	Quality Assurance	Check	SOP-120	View	View		12	

**Gyratory Compactor**

Action Status	Date	Technician	Certificate
Spare Equipment	10/26/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
259	FL2170	5155	Pine	AFGB1A	Quality Assurance	Check	SOP-120	View	View		12	

**Gyratory Compactor**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	1/9/2018	Lai, Binh 0057	

**Load Cell**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3607	135	389250	InstroTek	45 kN	InstroTek	Calibrate	OS100		View		12	

**Cracking Tolerance Index - Smart Jig**

Action Status	Date	Technician	Certificate
Spare Equipment	10/12/2023	Corbin, Roger B. Jr. 3424	
In Service	9/26/2022	McCullough, Donald 0004	
Calibrate	9/20/2022	External Agency	View
Standardize	9/20/2022	External Agency	View

**LVDT**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
316	135	023261	NovoTechnik	TR-0025	InstroTek	Calibrate	OS100		View		12	

**Cracking Tolerance Index - Smart Jig**

Action Status	Date	Technician	Certificate
Spare Equipment	10/12/2023	Corbin, Roger B. Jr. 3424	
In Service	9/26/2022	McCullough, Donald 0004	
Calibrate	9/20/2022	External Agency	View
Out of Service for Repair	8/26/2021	McCullough, Donald 0004	
Calibrate	8/26/2020	External Agency	View
Calibrate	10/16/2019	External Agency	View

**Micro Deval**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
691	Set #1 Control	1 Control	Gilson	HMA-922	Quality Assurance	Check	SOP-104	View	View		12	

**Steel Balls**

Action Status	Date	Technician	Certificate
Check	6/22/2022	Lai, Binh 0057	View
Check	6/24/2021	Lai, Binh 0057	View
Check	1/29/2021	Lai, Binh 0057	View
Check	3/23/2020	Lai, Binh 0057	View
Check	3/9/2019	Lai, Binh 0057	

## Moisture Induce Sensitivity Test

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
451	LR0157	71	InstroTEK	MIST	Calibration Solutions	Calibrate	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

### Moisture Induce Sensitivity Test

Action Status	Date	Technician	Certificate
Spare Equipment	8/31/2021	McCullough, Donald 0004	
Calibrate	8/27/2020	External Agency	<a href="#">View</a>
Calibrate	10/14/2019	External Agency	<a href="#">View</a>
Calibrate	8/2/2019	External Agency	
Calibrate	6/26/2018	External Agency	

## Shakers

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
415	S1100304	1341	Gilson	SGA-5R	Quality Assurance	Check	SOP-119	<a href="#">View</a>	<a href="#">View</a>	<a href="#">View</a>	12	

### Rice Shakers

Action Status	Date	Technician	Certificate
Spare Equipment	7/21/2022	McCullough, Donald 0004	
Check	6/21/2022	Lai, Binh 0057	<a href="#">View</a>
Check	6/16/2021	Lai, Binh 0057	<a href="#">View</a>
Check	12/18/2020	Lai, Binh 0057	<a href="#">View</a>
Check	12/5/2019	Lai, Binh 0057	
Check	12/5/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
414	S1100305	1342	Gilson	SGA-5R	Quality Assurance	Check	SOP-119	View	View	View	12	

**Rice Shakers**

Action Status	Date	Technician	Certificate
Spare Equipment	7/21/2022	McCullough, Donald 0004	
Check	6/21/2022	Lai, Binh 0057	<a href="#">View</a>
Check	6/16/2021	Lai, Binh 0057	<a href="#">View</a>
Check	12/18/2020	Lai, Binh 0057	<a href="#">View</a>
Check	12/5/2019	Lai, Binh 0057	
Check	12/5/2018	Lai, Binh 0057	

**Sieves**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2139	SET-20	1268573	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

**12" (#80)**

Action Status	Date	Technician	Certificate
Spare Equipment	6/29/2021	McCullough, Donald 0004	
Check	7/15/2020	Lai, Binh 0057	<a href="#">View</a>
Check	7/17/2019	Lai, Binh 0057	

**Thermometers**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
729	080089	080089-12-C	Omega	HH804U	Calibration Solutions	Standardize	OS100		View		12	

**Probe#03/Red/Red/12"**

Action Status	Date	Technician	Certificate
Spare Equipment	7/25/2022	McCullough, Donald 0004	
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/26/2020	External Agency	<a href="#">View</a>
Standardize	10/17/2019	External Agency	<a href="#">View</a>
Standardize	3/28/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1257	080098	080098-18	Omega	HH804U	Calibration Solutions	Standardize	OS100		<a href="#">View</a>		12	

Probe#01/Blue/Red/18"

Action Status	Date	Technician	Certificate
Spare Equipment	7/25/2022	McCullough, Donald 0004	
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/26/2020	External Agency	<a href="#">View</a>
Standardize	10/17/2019	External Agency	<a href="#">View</a>
Standardize	3/28/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3504	210328	210328	Omega	HH804U	Quality Assurance	Standardize	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

Digital Display

Action Status	Date	Technician	Certificate
Spare Equipment	7/25/2022	McCullough, Donald 0004	
Standardize	2/9/2022	Lai, Binh 0057	<a href="#">View</a>
In Service	2/9/2022	McCullough, Donald 0004	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1201	486034	486034	Digi-Sense	Type K	Calibration Solutions	Standardize	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

Digital Display

Action Status	Date	Technician	Certificate
Spare Equipment	7/25/2022	McCullough, Donald 0004	
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/26/2020	External Agency	<a href="#">View</a>
Standardize	10/14/2019	External Agency	<a href="#">View</a>
Standardize	6/6/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1800	LAT0266-C0A042	C0A042	Fluke	5611T	Fluke	Standardize	OS100				12	

**Probe#31/Thermister**

Action Status	Date	Technician	Certificate
Spare Equipment	6/2/2021	McCullough, Donald 0004	
Standardize	1/11/2021	External Agency	<a href="#">View</a>

### Variable Length Measurement

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
704	0000724	0000724	Mitutoyo	151-272	Calibration Solutions	Calibrate	OS100		<a href="#">View</a>		12	

**Micrometer Head**

Action Status	Date	Technician	Certificate
Spare Equipment	8/28/2023	McCullough, Donald 0004	
Calibrate	8/18/2022	External Agency	<a href="#">View</a>
Calibrate	8/27/2021	External Agency	<a href="#">View</a>
Calibrate	8/27/2020	External Agency	<a href="#">View</a>
Calibrate	10/16/2019	External Agency	<a href="#">View</a>
Calibrate	10/8/2018	External Agency	

### X-Ray

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3522	FL2477	115801	Thermo Scientific	XL3T 950		Check	<a href="/materials/C97001">/materials/C97001</a>	View	<a href="#">View</a>			

**X-Ray Fluorescence Spectrometer (Portable)**

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2021	McCullough, Donald 0004	

Lab Id Lab Name  
 94 Central Structural Materials Lab

**Coating Thickness Gauge**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3712	G0060	G0060	P. N. Gardner Co.	PosiTest	Quality Assurance	Check	SOP-170	View			12	

Integral

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/8/2023                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3711	G0068	G0068	P. N. Gardner Co.	PosiTest	Quality Assurance	Check	SOP-170	View			12	

Integral

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/8/2023                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
441	HC07837-028	HC07837-028	Elcometer	456	Quality Assurance	Check	SOP-170	View			12	

Display

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      3/29/2021                      McCullough, Donald                      0004  
 Check                      11/20/2020                      Lai, Binh                      0057                      [View](#)  
 Check                      11/21/2019                      Lai, Binh                      0057                      [View](#)

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
437	JF29406-012	JF29406-012	Elcometer	456	Quality Assurance	Check	SOP-170	View			12	

Display

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      6/2/2021                      McCullough, Donald                      0004  
 Check                      11/20/2020                      Lai, Binh                      0057                      [View](#)  
 Check                      11/21/2019                      Lai, Binh                      0057                      [View](#)



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1779	16251	KC43424-002	Elcometer	F1	Quality Assurance	Check	SOP-170	View			12	

Probe

Action Status	Date	Technician	Certificate
Spare Equipment	4/23/2021	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
442	HC07837-028 - P	KC43424-008	Elcometer	F1	Quality Assurance	Check	SOP-170	View			12	

Probe

Action Status	Date	Technician	Certificate
Spare Equipment	3/29/2021	McCullough, Donald 0004	
Check	11/20/2020	Lai, Binh 0057	<a href="#">View</a>
Check	11/21/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
438	JF29406-012 - P	KC43424-028	Elcometer	F1	Quality Assurance	Check	SOP-170	View			12	

Probe

Action Status	Date	Technician	Certificate
Spare Equipment	6/2/2021	McCullough, Donald 0004	
Check	11/20/2020	Lai, Binh 0057	<a href="#">View</a>
Check	11/21/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1749	G0084 - 4773 - P	TB16161	Elcometer	F1U	Quality Assurance	Check	SOP-170	View	View		12	

Probe

Action Status	Date	Technician	Certificate
Spare Equipment	2/4/2021	McCullough, Donald 0004	
Check	11/20/2020	Lai, Binh 0057	

### Dial or Digital Indicators

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
626	P-053	P-053	Mitutoyo	P-053	Calibration Solutions	Standardize	OS100		View		12	

Digital

Action Status	Date	Technician	Certificate
Spare Equipment	5/12/2021	McCullough, Donald 0004	
Standardize	8/26/2020	External Agency	<a href="#">View</a>
Standardize	10/11/2019	External Agency	<a href="#">View</a>
Standardize	10/8/2018	External Agency	<a href="#">View</a>

### Fine Agg Specific Gravity

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1837	CM-21	CM-21	Humboldt	H-3361	Quality Assurance	Check	SOP-147	View			24	

Conical mold

Action Status	Date	Technician	Certificate

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1836	CM-3	CM-3	Humboldt	H-3361	Quality Assurance	Check	SOP-147	View			24	

Conical mold

Action Status	Date	Technician	Certificate

## High Humidity Area

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
452	LAT0251 - MR1	MR1-TANKS	ODOT	Stirred	Quality Assurance	Check	<a href="/materials/C97001">/materials/C97001</a>	View			1	

### Cure Tank (Tank stir record Stru Lab)

Action Status	Date	Technician	Certificate
Spare Equipment	2/9/2024	McCullough, Donald 0004	
Check	1/2/2024	Lai, Binh 0057	
Check	12/4/2023	Lai, Binh 0057	<a href="#">View</a>
Check	11/1/2023	Lai, Binh 0057	<a href="#">View</a>
Check	10/4/2023	Lai, Binh 0057	<a href="#">View</a>
Check	9/1/2023	Lai, Binh 0057	<a href="#">View</a>
Check	8/2/2023	Lai, Binh 0057	<a href="#">View</a>
Check	7/3/2023	Lai, Binh 0057	<a href="#">View</a>
Check	6/1/2023	Lai, Binh 0057	<a href="#">View</a>
Check	5/1/2023	Lai, Binh 0057	<a href="#">View</a>
Check	4/3/2023	Lai, Binh 0057	<a href="#">View</a>
Check	3/1/2023	Lai, Binh 0057	<a href="#">View</a>
Check	2/1/2023	Lai, Binh 0057	<a href="#">View</a>
Check	1/3/2023	Lai, Binh 0057	<a href="#">View</a>
Check	12/1/2022	Lai, Binh 0057	<a href="#">View</a>
Check	11/1/2022	Lai, Binh 0057	<a href="#">View</a>
Check	10/3/2022	Lai, Binh 0057	<a href="#">View</a>
Check	9/1/2022	Lai, Binh 0057	<a href="#">View</a>
Check	8/1/2022	Lai, Binh 0057	<a href="#">View</a>
Check	7/1/2022	Lai, Binh 0057	<a href="#">View</a>
Check	6/1/2022	Lai, Binh 0057	<a href="#">View</a>
Check	5/2/2022	Lai, Binh 0057	<a href="#">View</a>
Check	4/4/2022	Lai, Binh 0057	<a href="#">View</a>
Check	3/1/2022	Lai, Binh 0057	<a href="#">View</a>
Check	2/1/2022	Lai, Binh 0057	<a href="#">View</a>
Check	1/3/2022	Lai, Binh 0057	<a href="#">View</a>
Check	12/1/2021	Lai, Binh 0057	<a href="#">View</a>
Check	11/3/2021	Lai, Binh 0057	<a href="#">View</a>
Check	10/7/2021	Lai, Binh 0057	<a href="#">View</a>
Check	9/4/2021	Lai, Binh 0057	<a href="#">View</a>
Check	8/9/2021	Lai, Binh 0057	<a href="#">View</a>
Check	7/9/2021	Lai, Binh 0057	<a href="#">View</a>
Check	6/8/2021	Lai, Binh 0057	<a href="#">View</a>
Check	5/10/2021	Lai, Binh 0057	<a href="#">View</a>

Check	4/12/2021	Lai, Binh	0057	<a href="#">View</a>
Check	3/12/2021	Lai, Binh	0057	<a href="#">View</a>
Check	2/19/2021	Lai, Binh	0057	<a href="#">View</a>
Check	1/11/2021	Crawford, David	3494	<a href="#">View</a>
Check	12/7/2020	Crawford, David	3494	<a href="#">View</a>
Check	11/9/2020	Lai, Binh	0057	<a href="#">View</a>
Check	10/14/2020	Lai, Binh	0057	<a href="#">View</a>
In Service	9/28/2020	McCullough, Donald	0004	
Check	9/22/2020	Lai, Binh	0057	<a href="#">View</a>
Check	9/9/2020	Lai, Binh	0057	<a href="#">View</a>
Check	10/16/2019	Lai, Binh	0057	<a href="#">View</a>

## Meters

### Spare Equipment

Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	Freq.	Calib. Due Dt.
											(Months)	
3679	#4	LAE0470	Gilson	HM-30S	Structural Branch	Standardize	SOP-168	View			3	

#### Air Meter (Pressure)

Action Status	Date	Technician	Certificate
Spare Equipment	7/19/2023	McCullough, Donald 0004	
Standardize	7/13/2023	Lai, Binh 0057	<a href="#">View</a>
In Service	4/20/2023	McCullough, Donald 0004	
Standardize	4/3/2023	Lai, Binh 0057	<a href="#">View</a>

### Spare Equipment

Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	Freq.	Calib. Due Dt.
											(Months)	
31	LAE0557	LAE0557	Gilson	HM-30S	Structural Branch	Standardize	SOP-168	View		View	3	

#### Air Meter (Pressure)

Action Status	Date	Technician	Certificate
Spare Equipment	3/30/2021	Groom, Michael D. 2629	
Out of Service for Repair	2/17/2021	McCullough, Donald 0004	
Standardize	11/23/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	8/14/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	5/21/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	1/7/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	10/18/2019	Crawford, David 3494	<a href="#">View</a>
Standardize	7/16/2019	Crawford, David 3494	<a href="#">View</a>
Standardize	4/12/2019	Crawford, David 3494	<a href="#">View</a>
Standardize	1/15/2019	Crawford, David 3494	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
30	LAT0112	LAT0112	Forney	H-3195	Structural Branch	Calibrate	SOP-162	View	View	View	12	

**Air Meter (Volumetric)**

Action Status	Date	Technician	Certificate
Spare Equipment	12/8/2020	Groom, Michael D. 2629	
Calibrate	5/22/2020	Lai, Binh 0057	<a href="#">View</a>
Calibrate	5/8/2019	Crawford, David 3494	

**Ovens and Furnaces**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3451	LO0438	48364	Concrete Phoenix	S1794	Quality Assurance	Check	SOP-185	View	View	View	12	

**Concrete Drying KILN**

Action Status	Date	Technician	Certificate
Spare Equipment	11/5/2021	McCullough, Donald 0004	
In Service	11/4/2021	McCullough, Donald 0004	

**Scales**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3454	LO0438	AEA95596	Adam Equipmant	CKT16UH	Quality Assurance	Check	SOP-185	View	View		12	

**Concrete Drying KILN (weighing scale)**

Action Status	Date	Technician	Certificate
Spare Equipment	11/5/2021	McCullough, Donald 0004	

## Shakers

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3457	S1100302	S1100302	RainHart	637D	Quality Assurance	Check	<a href="#">SOP-111</a>	View			12	

Sieve - Round

Action Status	Date	Technician	Certificate
Spare Equipment	11/18/2021	McCullough, Donald	0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3673	S1100320	S1100320	Humboldt	H-4374	Quality Assurance	Check	<a href="#">SOP-113</a>	View			12	

Sand Equivalent Apparatus

Action Status	Date	Technician	Certificate

## Sieves

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2137	Set#50	01268564	Gilson	UNKNOWN	Calibration Solutions	Check	<a href="#">OS100</a>				12	

12" (#30)

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald	0004
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/17/2022	External Agency	<a href="#">View</a>
Check	8/27/2021	External Agency	<a href="#">View</a>
Check	9/14/2020	Lai, Binh	0057 <a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3690	02258542	02258542	W.S. Tyler	8"FHSS#200	Calibration Solutions	Check	OS100				12	

8" (#200)

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	6/7/2023	Lai, Binh 0057	<a href="#">View</a>
In Service	6/6/2023	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2654	03159375	03159375	Gilson	V12CI#10	Calibration Solutions	Check	OS100				12	

12" (#10)

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/18/2022	External Agency	<a href="#">View</a>
Check	1/5/2022	McCullough, Donald 0004	<a href="#">View</a>
In Service	1/5/2022	McCullough, Donald 0004	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1936	Set#41	06139639	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	9/29/2020	McCullough, Donald 0004	
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1953	Set#48	06180158	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#100)

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/18/2022	External Agency	<a href="#">View</a>
Check	1/5/2022	McCullough, Donald 0004	<a href="#">View</a>
In Service	1/4/2022	McCullough, Donald 0004	
Spare Equipment	9/2/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1959	Set#41	06409395	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#20)

Action Status	Date	Technician	Certificate
Spare Equipment	9/29/2020	McCullough, Donald 0004	
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1960	Set#41	06409396	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status	Date	Technician	Certificate
Spare Equipment	9/29/2020	McCullough, Donald 0004	
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1964	Set#41	07159004	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#8)

Action Status	Date	Technician	Certificate
Spare Equipment	9/29/2020	McCullough, Donald 0004	
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1966	Set#41	071710540	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#4)

Action Status	Date	Technician	Certificate
Spare Equipment	9/29/2020	McCullough, Donald 0004	
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1970	Set#41	07179073	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/8")

Action Status	Date	Technician	Certificate
Spare Equipment	9/29/2020	McCullough, Donald 0004	
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1971	Set#41	07179463	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#16)

Action Status	Date	Technician	Certificate
Spare Equipment	9/29/2020	McCullough, Donald 0004	
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1998	Set#41	09389413	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status	Date	Technician	Certificate
Spare Equipment	9/29/2020	McCullough, Donald 0004	
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2000	Set#41	09436540	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#200)

Action Status	Date	Technician	Certificate
Spare Equipment	9/29/2020	McCullough, Donald 0004	
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2016	Set#42	10278526	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (3/8")

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/18/2022	External Agency	<a href="#">View</a>
Check	8/27/2021	External Agency	<a href="#">View</a>
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2020	Set#44	10278530	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#4)

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/17/2022	External Agency	<a href="#">View</a>
Check	8/27/2021	External Agency	<a href="#">View</a>
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2021	Set#42	10278531	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#8)

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/18/2022	External Agency	<a href="#">View</a>
Check	8/27/2021	External Agency	<a href="#">View</a>
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2022	Set#44	10278532	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#8)

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/17/2022	External Agency	<a href="#">View</a>
Check	8/27/2021	External Agency	<a href="#">View</a>
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2028	Set#42	10278542	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/18/2022	External Agency	<a href="#">View</a>
Check	8/27/2021	External Agency	<a href="#">View</a>
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2030	Set#42	10279440	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#100)

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Spare Equipment	8/19/2022	McCullough, Donald 0004	
Check	8/19/2022	External Agency	
In Service	8/18/2022	McCullough, Donald 0004	<a href="#">View</a>
Check	8/18/2022	External Agency	<a href="#">View</a>
Check	8/27/2021	External Agency	<a href="#">View</a>
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2254	AG1-100A	154514221	Gilson	V12CH#100	Calibration Solutions	Check	OS100				12	

12" (#100)

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/18/2022	External Agency	<a href="#">View</a>
Check	11/16/2021	Lai, Binh 0057	<a href="#">View</a>
In Service	11/15/2021	McCullough, Donald 0004	
Spare Equipment	4/30/2021	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3241	16-16	16-16	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#16)

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
In Service	8/31/2022	McCullough, Donald 0004	<a href="#">View</a>
Check	8/31/2022	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3474	Set#48	213925970	Gilson	V12SI #200	Calibration Solutions	Check	OS100				12	

12" (#200)

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/18/2022	External Agency	<a href="#">View</a>
Check	1/5/2022	McCullough, Donald 0004	<a href="#">View</a>
In Service	1/4/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3475	Set#48	214222305	Gilson	V12CI 3/4"	Calibration Solutions	Check	OS100				12	

12" (3/4")

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/17/2022	External Agency	<a href="#">View</a>
Check	1/5/2022	McCullough, Donald 0004	<a href="#">View</a>
In Service	1/4/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3559	220420229	220420229	Gilson	V8CF #200	Calibration Solutions	Check	OS100				12	

8" (#200)

Action Status	Date	Technician	Certificate
Spare Equipment	5/12/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3560	220420232	220420232	Gilson	V8CF #200	Calibration Solutions	Check	OS100				12	

8" (#200)

Action Status	Date	Technician	Certificate
Spare Equipment	5/12/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2525	Set#49	65912F676559	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#6)

Action Status	Date	Technician	Certificate
Spare Equipment	9/29/2020	McCullough, Donald 0004	
Check	9/14/2020	Lai, Binh 0057	<a href="#">View</a>
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2560	dummy	89456	Soiltest	Unknown	Calibration Solutions	Check	OS100				12	

8" (1 1/2")

Action Status	Date	Technician	Certificate
Spare Equipment	9/29/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2767	AD#13	AD#13	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (3/8")

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
In Service	8/31/2022	McCullough, Donald 0004	<a href="#">View</a>
Check	8/31/2022	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3448	AG1	AG1-1/2A	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (1/2")

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/18/2022	External Agency	<a href="#">View</a>
In Service	10/15/2021	McCullough, Donald 0004	
Check	8/27/2021	External Agency	<a href="#">View</a>
	8/3/2021	Lai, Binh 0057	<a href="#">View</a>
Check	8/3/2021	Lai, Binh 0057	<a href="#">View</a>
In Service	8/2/2021	McCullough, Donald 0004	
Spare Equipment	9/10/2020	McCullough, Donald 0004	
	11/20/2019	Lai, Binh 0057	
Check	11/20/2019	Lai, Binh 0057	
	11/21/2018	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3444	AG1	AG1-1A	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (1")

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/18/2022	External Agency	<a href="#">View</a>
In Service	10/15/2021	McCullough, Donald 0004	
Check	8/27/2021	External Agency	<a href="#">View</a>
Check	8/3/2021	Lai, Binh 0057	<a href="#">View</a>
	8/3/2021	Lai, Binh 0057	<a href="#">View</a>
In Service	8/2/2021	McCullough, Donald 0004	
Spare Equipment	9/10/2020	McCullough, Donald 0004	
	11/20/2019	Lai, Binh 0057	
Check	11/20/2019	Lai, Binh 0057	
	11/21/2018	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3445	AG1	AG4-1.5A	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (1 1/2")

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/18/2022	External Agency	<a href="#">View</a>
In Service	10/15/2021	McCullough, Donald 0004	
Check	8/27/2021	External Agency	<a href="#">View</a>
Check	8/3/2021	Lai, Binh 0057	<a href="#">View</a>
	8/3/2021	Lai, Binh 0057	<a href="#">View</a>
In Service	8/2/2021	McCullough, Donald 0004	
Spare Equipment	9/10/2020	McCullough, Donald 0004	
	11/20/2019	Lai, Binh 0057	
Check	11/20/2019	Lai, Binh 0057	
	11/21/2018	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3705	G	G 3/4-8	Gilson	TSA100 3/4	Calibration Solutions	Check	OS100				12	

16"X24" (3/4")

Action Status	Date	Technician	Certificate
Spare Equipment	8/29/2023	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3410	Set#44	STL-1	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" Lid

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/18/2022	External Agency	<a href="#">View</a>
In Service	8/30/2021	McCullough, Donald 0004	
Check	8/27/2021	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3402	Set#50	STP-3	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" Pan

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/18/2022	External Agency	<a href="#">View</a>
In Service	8/30/2021	McCullough, Donald 0004	
Check	8/27/2021	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3403	AG1	STP-4	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" Pan

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Spare Equipment	8/19/2022	McCullough, Donald 0004	
Check	8/19/2022	External Agency	
Check	8/18/2022	External Agency	<a href="#">View</a>
In Service	8/18/2022	McCullough, Donald 0004	<a href="#">View</a>
In Service	8/30/2021	McCullough, Donald 0004	
Check	8/27/2021	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3404	Set#46	STP-5	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" Pan

Action Status	Date	Technician	Certificate
Spare Equipment	10/26/2022	McCullough, Donald 0004	
In Service	8/30/2021	McCullough, Donald 0004	
Check	8/27/2021	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3473	STP-5-1	STP-5-1	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" Pan

Action Status	Date	Technician	Certificate
Spare Equipment	10/3/2023	McCullough, Donald 0004	
Check	8/30/2023	External Agency	<a href="#">View</a>
Check	8/18/2022	External Agency	<a href="#">View</a>
Check	1/5/2022	McCullough, Donald 0004	<a href="#">View</a>
In Service	1/4/2022	McCullough, Donald 0004	

## Specific Gravity

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1746	PF16	PF16	Pyrex	5600	Quality Assurance	Standardize	SOP-191	View			12	

500mL

Action Status	Date	Technician	Certificate
Spare Equipment	1/11/2021	McCullough, Donald 0004	

## Tamping Tools

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
552	STR-5	STR-5	Humboldt	H-2905.1	Quality Assurance	Check	SOP-149	View	View		12	

Rod - small

Action Status	Date	Technician	Certificate
Spare Equipment	8/16/2023	McCullough, Donald 0004	
Check	8/16/2022	Lai, Binh 0057	<a href="#">View</a>
Check	8/16/2021	Lai, Binh 0057	<a href="#">View</a>
Check	11/16/2020	Lai, Binh 0057	<a href="#">View</a>
Check	11/12/2019	Lai, Binh 0057	<a href="#">View</a>
Check	11/14/2018	Lai, Binh 0057	<a href="#">View</a>

## Variable Length Measurement

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
703	S0480075	18018668	Starrett	760	Quality Assurance	Check	SOP-105	View	View	View	12	

Micrometer 1"

Action Status	Date	Technician	Certificate
Spare Equipment	12/4/2018	Groom, Michael D. 2629	<a href="#">View</a>
Check	12/4/2018	Lai, Binh 0057	<a href="#">View</a>

Lab Id 95 Lab Name Central Geotechnical Lab

**California Bearing Ratio**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
77	Set11	11-CBR	Gilson	BRA-60	Quality Assurance	Check	SOP-177	View	View		12	

**Mold, Plate, Weights & Spacer Disk**

Action Status	Date	Technician	Certificate
Spare Equipment	11/30/2020	Groom, Michael D. 2629	
Check	1/16/2020	Lai, Binh 0057	<a href="#">View</a>
Check	1/24/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
71	Set13	13-CBR	Gilson	BRA-60	Quality Assurance	Check	SOP-177	View	View		12	

**Mold, Plate, Weights & Spacer Disk**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
73	Set14	14-CBR	Gilson	BRA-60	Quality Assurance	Check	SOP-177	View	View		12	

**Mold, Plate, Weights & Spacer Disk**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
72	Set15	15-CBR	Gilson	BRA-60	Quality Assurance	Check	SOP-177	View	View		12	

**Mold, Plate, Weights & Spacer Disk**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
75	Set01	1-CBR	Gilson	BRA-60	Quality Assurance	Check	SOP-177	View	View		12	

**Mold, Plate, Weights & Spacer Disk**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
74	Set09	9-CBR	Gilson	BRA-60	Quality Assurance	Check	SOP-177	View	View		12	

**Mold, Plate, Weights & Spacer Disk**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	11/21/2018	Lai, Binh 0057	

**Consolidometers**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
160	FL1797	105702	Wykeham-Farrance	24002	Geotechnical Branch	Calibrate	Needs Procedure	View	View		12	

**WF Apparatus**

Action Status	Date	Technician	Certificate
Spare Equipment	9/20/2021	Groom, Michael D. 2629	
Calibrate	10/18/2019	Clarke, Christopher R. 0006	View
Out of Service for Repair	8/26/2019	McCullough, Donald 0004	
Calibrate	7/18/2018	Clarke, Christopher R. 0006	View

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
162	FL1815	96560-6	Wykeham-Farrance	24001	Geotechnical Branch	Calibrate	SOP-196	View	View		12	

**WF Apparatus**

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2021	Groom, Michael D. 2629	
Calibrate	1/28/2021	Clarke, Christopher R. 0006	<a href="#">View</a>
Calibrate	10/18/2019	Clarke, Christopher R. 0006	<a href="#">View</a>
Out of Service for Repair	8/26/2019	McCullough, Donald 0004	
Calibrate	8/28/2018	Clarke, Christopher R. 0006	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1703	FL1815 Set 3	WFW3	Wykeham-Farrance	WF 24001	Geotechnical Branch	Check	SOP-196	View	View		12	

**Weights WF**

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2021	Groom, Michael D. 2629	
Check	11/18/2020	McCullough, Donald 0004	<a href="#">View</a>
Calibrate	11/18/2020	McCullough, Donald 0004	<a href="#">View</a>
Check	10/18/2019	Lai, Binh 0057	
Calibrate	10/18/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1704	FL1797 Set 4	WFW4	Wykeham-Farrance	WF 24002	Geotechnical Branch	Check	SOP-197	View	View		12	

**Weights WF**

Action Status	Date	Technician	Certificate
Spare Equipment	10/4/2021	McCullough, Donald 0004	
Calibrate	11/18/2020	McCullough, Donald 0004	<a href="#">View</a>
Check	11/18/2020	McCullough, Donald 0004	<a href="#">View</a>
Out of Service for Repair	8/26/2019	McCullough, Donald 0004	

**Dial or Digital Indicators**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
633	001456267	001456267	Humboldt	BG2500016	Calibration Solutions	Standardize	OS100		View		12	

**Digital**

Action Status	Date	Technician	Certificate
Spare Equipment	9/21/2023	McCullough, Donald 0004	
Standardize	8/16/2022	External Agency	<a href="#">View</a>
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/25/2020	External Agency	<a href="#">View</a>
Standardize	10/15/2019	External Agency	<a href="#">View</a>
Standardize	10/8/2018	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
642	001969519	001969519	Humboldt	BG2600016	Calibration Solutions	Standardize	OS100		View		12	

**Digital**

Action Status	Date	Technician	Certificate
Spare Equipment	9/21/2023	McCullough, Donald 0004	
Standardize	8/16/2022	External Agency	<a href="#">View</a>
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/25/2020	External Agency	<a href="#">View</a>
Standardize	10/15/2019	External Agency	<a href="#">View</a>
Standardize	10/8/2018	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
637	010967469	010967469	Humboldt	BG3500016	Calibration Solutions	Standardize	OS100		View		12	

**Digital**

Action Status	Date	Technician	Certificate
Standardize	8/16/2022	External Agency	<a href="#">View</a>
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/25/2020	External Agency	<a href="#">View</a>
Standardize	10/15/2019	External Agency	<a href="#">View</a>
Standardize	10/10/2018	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
627	066877	066877	Mitutoyo	2358-50	Calibration Solutions	Standardize	OS100		<a href="#">View</a>		12	

Dial

Action Status	Date	Technician	Certificate
Spare Equipment	8/31/2021	McCullough, Donald 0004	
Standardize	8/24/2020	External Agency	<a href="#">View</a>
Standardize	10/15/2019	External Agency	<a href="#">View</a>
Standardize	10/8/2018	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
632	180460637	180460637	Humboldt	Q2500-0-16	Calibration Solutions	Standardize	OS100		<a href="#">View</a>		12	

Digital

Action Status	Date	Technician	Certificate
Spare Equipment	9/21/2023	McCullough, Donald 0004	
Standardize	8/16/2022	External Agency	<a href="#">View</a>
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/25/2020	External Agency	<a href="#">View</a>
Standardize	10/15/2019	External Agency	<a href="#">View</a>
Standardize	10/8/2018	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
645	181024947	181024947	Humboldt	Q2600-0-16	Calibration Solutions	Standardize	OS100		<a href="#">View</a>		12	

Digital

Action Status	Date	Technician	Certificate
Spare Equipment	9/21/2023	McCullough, Donald 0004	
Standardize	8/16/2022	External Agency	<a href="#">View</a>
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/25/2020	External Agency	<a href="#">View</a>
Standardize	10/15/2019	External Agency	<a href="#">View</a>
Standardize	10/8/2018	External Agency	<a href="#">View</a>



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
640	981914725	981914725	Humboldt	BG2500016	Calibration Solutions	Standardize	OS100		View		12	

**Digital**

Action Status	Date	Technician	Certificate
Spare Equipment	9/21/2023	McCullough, Donald 0004	
Standardize	8/16/2022	External Agency	<a href="#">View</a>
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/25/2020	External Agency	<a href="#">View</a>
Standardize	10/15/2019	External Agency	<a href="#">View</a>
Standardize	10/8/2018	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
641	991961879	991961879	Humboldt	BG2500016	Calibration Solutions	Standardize	OS100		View		12	

**Digital**

Action Status	Date	Technician	Certificate
Spare Equipment	9/21/2023	McCullough, Donald 0004	
Standardize	8/16/2022	External Agency	<a href="#">View</a>
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/25/2020	External Agency	<a href="#">View</a>
Standardize	10/15/2019	External Agency	<a href="#">View</a>
Standardize	10/8/2018	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
628	F	F	Starrett	25-441	Calibration Solutions	Check	OS100		<a href="#">View</a>		12	

Dial

Action Status	Date	Technician	Certificate
Spare Equipment	9/21/2023	McCullough, Donald 0004	
Standardize	8/16/2022	McCullough, Donald 0004	<a href="#">View</a>
Check	8/16/2022	McCullough, Donald 0004	<a href="#">View</a>
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Check	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/24/2020	External Agency	<a href="#">View</a>
Check	8/24/2020	External Agency	<a href="#">View</a>
Standardize	10/15/2019	External Agency	<a href="#">View</a>
Check	10/15/2019	External Agency	<a href="#">View</a>
Standardize	10/8/2018	External Agency	<a href="#">View</a>
Check	10/8/2018	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
163	FL0279 Set 1	S-021	ODOT	Shop made	Calibration Solutions	Calibrate	Needs Procedure	<a href="#">View</a>	<a href="#">View</a>		12	

Digital

Action Status	Date	Technician	Certificate
Spare Equipment	7/16/2021	Groom, Michael D. 2629	
Calibrate	8/25/2020	External Agency	<a href="#">View</a>
Calibrate	1/9/2020	Clarke, Christopher R. 0006	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1269	FL0279 Set 2	S-022	ODOT	Shop made	Calibration Solutions	Calibrate	Needs Procedure	<a href="#">View</a>	<a href="#">View</a>		12	

Digital

Action Status	Date	Technician	Certificate
Spare Equipment	7/16/2021	Groom, Michael D. 2629	
Calibrate	8/26/2020	External Agency	<a href="#">View</a>
In Service	8/20/2020	Groom, Michael D. 2629	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1270	FL0279 Set 3	S-023	ODOT	Shop made	Calibration Solutions	Calibrate	Needs Procedure	View	View		12	

Digital

Action Status	Date	Technician	Certificate
Spare Equipment	7/16/2021	Groom, Michael D. 2629	
Calibrate	8/25/2020	External Agency	View
Calibrate	1/9/2020	Clarke, Christopher R. 0006	View

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1271	FL0279 Set 4	S-040	ODOT	Shop made	Calibration Solutions	Calibrate	Needs Procedure	View	View		12	

Digital

Action Status	Date	Technician	Certificate
Spare Equipment	7/16/2021	Groom, Michael D. 2629	
Calibrate	8/25/2020	External Agency	View
Calibrate	1/9/2020	Clarke, Christopher R. 0006	View

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1272	FL0279 Set 5	S-041	ODOT	Shop made	Calibration Solutions	Calibrate	Needs Procedure	View	View		12	

Digital

Action Status	Date	Technician	Certificate
Spare Equipment	7/16/2021	Groom, Michael D. 2629	
Calibrate	8/26/2020	External Agency	View
In Service	8/20/2020	Groom, Michael D. 2629	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1273	FL0279 Set 6	S-042	ODOT	Shop made	Calibration Solutions	Calibrate	Needs Procedure	View	View		12	

Digital

Action Status	Date	Technician	Certificate
Spare Equipment	7/16/2021	Groom, Michael D. 2629	
Calibrate	8/25/2020	External Agency	View
In Service	8/20/2020	Groom, Michael D. 2629	

## Durability

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1318	AD2	AD2	Gilson	SSA-22	Quality Assurance	Check	SOP-100	View			12	

### Aggregate Durability Wash Vessel

Action Status	Date	Technician	Certificate
Spare Equipment	8/22/2023	McCullough, Donald 0004	
Check	8/17/2023	Lai, Binh 0057	<a href="#">View</a>

## Gauges

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
202	FL1536	1515856	Wika	10 Bar	oss Precision Measureme	Calibrate	OS100		View		12	

### Dilatometer Panel Gauge (10 Bar)

Action Status	Date	Technician	Certificate
Spare Equipment	9/27/2021	McCullough, Donald 0004	
Calibrate	5/12/2021	External Agency	<a href="#">View</a>
Calibrate	6/8/2020	External Agency	<a href="#">View</a>
Calibrate	6/5/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
203	FL1536	1515856A	Wika	60 Bar	oss Precision Measureme	Calibrate	OS100		View		12	

### Dilatometer Panel Gauge (60 Bar)

Action Status	Date	Technician	Certificate
Spare Equipment	9/27/2021	McCullough, Donald 0004	
Calibrate	5/12/2021	External Agency	<a href="#">View</a>
Calibrate	6/8/2020	External Agency	<a href="#">View</a>
Calibrate	6/5/2019	External Agency	

## Glass Cylinder

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3430	None	GC01	Pyrex	Unknown	Quality Assurance	Check	SOP-109	View			12	

1000mL

Action Status	Date	Technician	Certificate
Spare Equipment	10/13/2021	McCullough, Donald 0004	

## Liquid Limit

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3592	52	52-LLGT	ELE	EL 24-0461	Quality Assurance	Check	SOP-174	View	View		12	

Grooving Tool (Curved)

Action Status	Date	Technician	Certificate
Spare Equipment	8/25/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1776	LL0001	LL0001	Humboldt	H-4230	Quality Assurance	Check	SOP-173	View	View		12	

Device

Action Status	Date	Technician	Certificate
Spare Equipment	4/20/2021	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1777	LL0002	LL0002	Humboldt	H-4230	Quality Assurance	Check	SOP-173	View	View		12	

Device

Action Status	Date	Technician	Certificate
Spare Equipment	10/6/2022	McCullough, Donald 0004	
Check	10/5/2021	Lai, Binh 0057	View
Check	8/3/2021	Lai, Binh 0057	View
In Service	8/3/2021	McCullough, Donald 0004	View
Spare Equipment	4/20/2021	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
305	7	LLHB-7	Humboldt	H-4229.2	Quality Assurance	Check	SOP-173	View	View		12	

**Height Gauge**

Action Status	Date	Technician	Certificate
Spare Equipment	10/6/2022	McCullough, Donald 0004	
Check	10/5/2022	Lai, Binh 0057	<a href="#">View</a>
In Service	10/4/2022	McCullough, Donald 0004	
Equipment Consolidated	12/11/2020	McCullough, Donald 0004	
Check	12/9/2020	Lai, Binh 0057	<a href="#">View</a>
Check	12/9/2019	Lai, Binh 0057	<a href="#">View</a>
Check	1/23/2019	Lai, Binh 0057	

**Load Cell**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
312	J19573	J19573	Geotest Instrument	DBBP-5000	Calibration Solutions	Calibrate	OS100		View		12	

**California Bearing Ratio**

Action Status	Date	Technician	Certificate
Calibrate	7/25/2019	External Agency	

**Metal Ruler**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
674	081010474	081010474	Fowler	09919-32	Quality Assurance	Check	SOP-110	View	View		12	

Set 3 24"

Action Status	Date	Technician	Certificate
Spare Equipment	9/19/2023	McCullough, Donald 0004	
Standardize	10/11/2022	Lai, Binh 0057	<a href="#">View</a>
Check	10/11/2022	Lai, Binh 0057	<a href="#">View</a>
Standardize	10/12/2021	Lai, Binh 0057	<a href="#">View</a>
Check	10/12/2021	Lai, Binh 0057	<a href="#">View</a>
Check	12/2/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	12/2/2020	Lai, Binh 0057	<a href="#">View</a>
Check	2/10/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	2/10/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	2/20/2019	Lai, Binh 0057	
Check	2/20/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
676	231010350	231010350	Fowler	09919-32	Quality Assurance	Check	SOP-110	View	View		12	

Set 3 12"

Action Status	Date	Technician	Certificate
Spare Equipment	9/19/2023	McCullough, Donald 0004	
Standardize	10/11/2022	Lai, Binh 0057	<a href="#">View</a>
Check	10/11/2022	Lai, Binh 0057	<a href="#">View</a>
Check	10/12/2021	Lai, Binh 0057	<a href="#">View</a>
Standardize	10/12/2021	Lai, Binh 0057	<a href="#">View</a>
Check	12/2/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	12/2/2020	Lai, Binh 0057	<a href="#">View</a>
Check	2/10/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	2/10/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	2/20/2019	Lai, Binh 0057	
Check	2/20/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
675	231010462	231010462	Fowler	09919-32	Quality Assurance	Check	SOP-110	View	View		12	

Set 3 6"

Action Status	Date	Technician	Certificate
Spare Equipment	9/19/2023	McCullough, Donald 0004	
Standardize	10/11/2022	Lai, Binh 0057	<a href="#">View</a>
Check	10/11/2022	Lai, Binh 0057	<a href="#">View</a>
Standardize	10/12/2021	Lai, Binh 0057	<a href="#">View</a>
Check	10/12/2021	Lai, Binh 0057	<a href="#">View</a>
Standardize	12/2/2020	Lai, Binh 0057	<a href="#">View</a>
Check	12/2/2020	Lai, Binh 0057	<a href="#">View</a>
Check	6/24/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	6/24/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	6/18/2019	Lai, Binh 0057	
Check	6/18/2019	Lai, Binh 0057	

**Micro Deval**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
696	Set#5	Set5 MDSB	Gilson	HMA-922	Quality Assurance	Check	SOP-104	View			12	

Steel Balls

Action Status	Date	Technician	Certificate
Spare Equipment	1/27/2022	McCullough, Donald 0004	
Calibrate	11/8/2021	Lai, Binh 0057	<a href="#">View</a>
Check	11/8/2021	Lai, Binh 0057	<a href="#">View</a>
Check	12/7/2020	Lai, Binh 0057	<a href="#">View</a>
Calibrate	12/7/2020	Lai, Binh 0057	<a href="#">View</a>
Check	3/23/2020	Lai, Binh 0057	<a href="#">View</a>
Calibrate	3/23/2020	Lai, Binh 0057	<a href="#">View</a>
Check	3/11/2019	Lai, Binh 0057	
Calibrate	3/11/2019	Lai, Binh 0057	



## Ovens and Furnaces

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
743	LO0392	607416-47	Thermo	6050	Quality Assurance	Check	SOP-182	View	View	View	12	

### Oven

Action Status	Date	Technician	Certificate
Spare Equipment	9/13/2021	McCullough, Donald 0004	
Standardize	11/20/2020	Lai, Binh 0057	<a href="#">View</a>
Check	11/20/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	8/11/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/11/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	8/6/2019	Lai, Binh 0057	
Check	8/6/2019	Lai, Binh 0057	

## Particle Size Analysis

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
275	11	11-SC	Kimax	1000 mL	Quality Assurance	Check	SOP-179	View	View		12	

### Sedimentation Cylinder

Action Status	Date	Technician	Certificate
Spare Equipment	8/22/2023	McCullough, Donald 0004	
Check	4/10/2023	Lai, Binh 0057	<a href="#">View</a>
In Service	4/4/2022	McCullough, Donald 0004	<a href="#">View</a>
Check	4/4/2022	Lai, Binh 0057	<a href="#">View</a>
Spare Equipment	10/13/2021	McCullough, Donald 0004	
Check	11/23/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/10/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/7/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
276	12	12-SC	Kimax	20023	Quality Assurance	Check	SOP-179	View	View		12	

**Sedimentation Cylinder**

Action Status	Date	Technician	Certificate
Spare Equipment	8/22/2023	McCullough, Donald 0004	
Spare Equipment	10/13/2021	McCullough, Donald 0004	
Check	11/23/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/10/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/7/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
277	13	13-SC	Kimax	20023	Quality Assurance	Check	SOP-179	View	View		12	

**Sedimentation Cylinder**

Action Status	Date	Technician	Certificate
Spare Equipment	10/13/2021	McCullough, Donald 0004	
Check	11/23/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/10/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/7/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
269	140759	140759	Chase	152H	Quality Assurance	Check	SOP-175	View	View		24	

**Hydrometer**

Action Status	Date	Technician	Certificate
Not In Use	7/6/2021	McCullough, Donald 0004	
In Service	12/7/2020	McCullough, Donald 0004	
Check	11/16/2020	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
280	16	16-SC	Kimax	20023	Quality Assurance	Check	SOP-179	View	View		12	

**Sedimentation Cylinder**

Action Status	Date	Technician	Certificate
Spare Equipment	10/13/2021	McCullough, Donald 0004	
Check	11/23/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/10/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/7/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3714	23	23-SC	Gilson	SA-5	Quality Assurance	Check	SOP-179	View			12	

**Sedimentation Cylinder**

Action Status	Date	Technician	Certificate
Spare Equipment	9/19/2023	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3715	24	24-SC	Gilson	SA-5	Quality Assurance	Check	SOP-179	View			12	

**Sedimentation Cylinder**

Action Status	Date	Technician	Certificate
Spare Equipment	9/19/2023	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3716	25	25-SC	Gilson	SA-5	Quality Assurance	Check	SOP-179	View			12	

**Sedimentation Cylinder**

Action Status	Date	Technician	Certificate
Spare Equipment	9/19/2023	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1731	26-1485	26-1485	SoilTest	152H	Quality Assurance	Check	SOP-175	View	View		24	

Hydrometer

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      12/7/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1729	26-1536	26-1536	SoilTest	152H	Quality Assurance	Check	SOP-175	View	View		24	

Hydrometer

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      12/7/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3717	26	26-SC	Gilson	SA-5	Quality Assurance	Check	SOP-179	View			12	

Sedimentation Cylinder

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/19/2023                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3718	27	27-SC	Gilson	SA-5	Quality Assurance	Check	SOP-179	View			12	

Sedimentation Cylinder

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/19/2023                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3719	28	28-SC	Gilson	SA-5	Quality Assurance	Check	SOP-179	View			12	

Sedimentation Cylinder

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/19/2023                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3720	29	29-SC	Gilson	SA-5	Quality Assurance	Check	SOP-179	View			12	

Sedimentation Cylinder

Action Status	Date	Technician	Certificate
Spare Equipment	9/19/2023	McCullough, Donald	0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
281	2	2-SC	Kimax	20023	Quality Assurance	Check	SOP-179	View	View		12	

Sedimentation Cylinder

Action Status	Date	Technician	Certificate
Spare Equipment	8/22/2023	McCullough, Donald	0004
Check	10/14/2022	Lai, Binh	0057 <a href="#">View</a>
Check	10/14/2021	Lai, Binh	0057 <a href="#">View</a>
Check	11/23/2020	Lai, Binh	0057 <a href="#">View</a>
Check	8/10/2020	Lai, Binh	0057 <a href="#">View</a>
Check	8/7/2019	Lai, Binh	0057

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3721	30	30-SC	Gilson	SA-5	Quality Assurance	Check	SOP-179	View			12	

Sedimentation Cylinder

Action Status	Date	Technician	Certificate
Spare Equipment	9/19/2023	McCullough, Donald	0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3722	31	31-SC	Gilson	SA-5	Quality Assurance	Check	SOP-179	View			12	

Sedimentation Cylinder

Action Status	Date	Technician	Certificate
Spare Equipment	9/19/2023	McCullough, Donald	0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1730	492	492	SoilTest	152H	Quality Assurance	Check	SOP-175	View	View		24	

**Hydrometer**

Action Status	Date	Technician	Certificate
Spare Equipment	12/7/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
283	4	4-SC	SoilTest	1000 mL	Quality Assurance	Check	SOP-179	View	View		12	

**Sedimentation Cylinder**

Action Status	Date	Technician	Certificate
Spare Equipment	8/22/2023	McCullough, Donald 0004	
Check	10/14/2022	Lai, Binh 0057	<a href="#">View</a>
Check	10/14/2021	Lai, Binh 0057	<a href="#">View</a>
Check	11/23/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/10/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/7/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1726	528042	528042	W.H. Curtin & Co.	67 degrees	Quality Assurance	Check	SOP-175	View			24	

**Hydrometer**

Action Status	Date	Technician	Certificate
Spare Equipment	12/7/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1728	533654	533654	W.H. Curtin & Co.	67 degrees	Quality Assurance	Check	SOP-175	View			24	

**Hydrometer**

Action Status	Date	Technician	Certificate
Spare Equipment	12/7/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
271	6	6-SC	Kimax	20023	Quality Assurance	Check	SOP-179	View	View		12	

**Sedimentation Cylinder**

Action Status	Date	Technician	Certificate
Spare Equipment	8/22/2023	McCullough, Donald 0004	
Check	10/14/2022	Lai, Binh 0057	<a href="#">View</a>
Check	10/14/2021	Lai, Binh 0057	<a href="#">View</a>
Check	11/23/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/10/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/7/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
274	8	8-SC	Kimax	1000 mL	Quality Assurance	Check	SOP-179	View	View		12	

**Sedimentation Cylinder**

Action Status	Date	Technician	Certificate
Spare Equipment	10/13/2021	McCullough, Donald 0004	
Check	11/23/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/10/2020	Lai, Binh 0057	<a href="#">View</a>
Check	8/7/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3535	10	DC10	Gilson	SA-16	Quality Assurance	Check	SOP-178	View			24	

**Dispersion Cup**

Action Status	Date	Technician	Certificate
Spare Equipment	4/14/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3533	8	DC8	Gilson	SA-16	Quality Assurance	Check	SOP-178	View			24	

**Dispersion Cup**

Action Status	Date	Technician	Certificate
Spare Equipment	4/14/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3534	9	DC9	Gilson	SA-16	Quality Assurance	Check	SOP-178	View			24	

Dispersion Cup

Action Status	Date	Technician	Certificate
Spare Equipment	4/14/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
286	Wash	Wash	Kimax	20023	Quality Assurance	Check	SOP-179	View	View		12	

Sedimentation Cylinder

Action Status	Date	Technician	Certificate
Spare Equipment	8/22/2023	McCullough, Donald 0004	
Check	10/14/2022	Lai, Binh 0057	View
Check	10/14/2021	Lai, Binh 0057	View
Check	11/23/2020	Lai, Binh 0057	View
Check	8/10/2020	Lai, Binh 0057	View
Check	8/7/2019	Lai, Binh 0057	

**Proctor**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
369	10-2012	10-2012	Humboldt	H-4161A	Quality Assurance	Check	SOP-172	View	View		12	

Mold 6" (Split Mold)

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	8/22/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
355	10-2012-4	10-2012-4	Gilson	HMA-111	Quality Assurance	Check	SOP-172	View	View		12	

**Mold 4" (Split Mold)**

Action Status	Date	Technician	Certificate
Spare Equipment	12/4/2018	Groom, Michael D. 2629	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3588	new	1-PSE-8	Humboldt	H-4144.8	Quality Assurance	Check	SOP-176	View	View		12	

**Straight Edge**

Action Status	Date	Technician	Certificate
Spare Equipment	8/25/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3589	new	2-PSE-8	Humboldt	H-4144.8	Quality Assurance	Check	SOP-176	View	View		12	

**Straight Edge**

Action Status	Date	Technician	Certificate
Spare Equipment	8/25/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3528	4	4-PSE	Humboldt	H-4144.12	Quality Assurance	Check	SOP-176	View	View		12	

**Straight Edge**

Action Status	Date	Technician	Certificate
Spare Equipment	3/29/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
379	5	5-PSE	Gilson	HMA-135	Quality Assurance	Check	SOP-176	View	View		12	

**Straight Edge**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	2/8/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
368	9-2012	9-2012	Gilson	HMA-117	Quality Assurance	Check	SOP-172	View	View		12	

**Mold 6" (Split Mold)**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	8/22/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
364	M-1	M-1	DGSI	S-325	Quality Assurance	Check	SOP-172	View	View		12	

**Mold 6" (Split Mold)**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
361	FL1390	M-133	Gilson	HMA-116	Quality Assurance	Check	SOP-172	View	View		12	

**Mold 6"**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	8/22/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
365	M-2	M-2	DGSI	S-325	Quality Assurance	Check	SOP-172	View	View		12	

**Mold 6" (Split Mold)**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
366	M-3	M-3	DGSI	S-325	Quality Assurance	Check	SOP-172	View	View		12	

**Mold 6" (Split Mold)**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
367	M-4	M-4	DGSI	S-325	Quality Assurance	Check	SOP-172	View	View		12	

**Mold 6" (Split Mold)**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
346	MR-1201	MR-1201	Humboldt	H-4173	Quality Assurance	Check	SOP-117	View	View		12	

**Manual Rammer 12"**

Action Status	Date	Technician	Certificate
Spare Equipment	10/13/2021	McCullough, Donald 0004	
Check	11/16/2020	Lai, Binh 0057	View
Check	11/21/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
348	MR-1801	MR-1801	Gilson	HM-556	Quality Assurance	Check	SOP-117	View	View		12	

**Manual Rammer 18"**

Action Status	Date	Technician	Certificate
Spare Equipment	10/13/2022	McCullough, Donald 0004	
Check	10/13/2021	Lai, Binh 0057	View
In Service	10/13/2021	McCullough, Donald 0004	View
Check	11/16/2020	Lai, Binh 0057	View
Check	11/21/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
360	PR-2	PR-2	Gilson	HMA-116	Quality Assurance	Check	SOP-172	View	View		12	

**Mold 6"**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
370	R1-A	R1-A	Rainhart	665-6-FMK	Quality Assurance	Check	SOP-172	View	View		12	

**Mold 6" X 4.584" + ring & funnel**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
358	S2435	S2435	Gilson	HMA-111	Quality Assurance	Check	SOP-172	View	View		12	

**Mold 4" (Split Mold)**

Action Status	Date	Technician	Certificate
Spare Equipment	8/9/2021	McCullough, Donald 0004	
Check	11/16/2020	Lai, Binh 0057	View
Check	11/20/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

## Proving Rings

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
384	13975	13975	Wykeham-Farrance	UNKNOWN	Calibration Solutions	Calibrate	OS100		View		12	

### Proving Ring (Digital Indicator 981803262)

Action Status	Date	Technician	Certificate
Spare Equipment	9/21/2023	McCullough, Donald 0004	
Calibrate	8/17/2022	External Agency	<a href="#">View</a>
Calibrate	8/27/2021	External Agency	<a href="#">View</a>
Calibrate	8/26/2020	External Agency	<a href="#">View</a>
Calibrate	10/16/2019	External Agency	<a href="#">View</a>
Calibrate	10/8/2018	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
394	21786	21786	Humboldt	BG2500016	Calibration Solutions	Calibrate	OS100		View		12	

### Proving Ring (Dial Wykeham Farrance)

Action Status	Date	Technician	Certificate
Spare Equipment	9/2/2021	McCullough, Donald 0004	
Calibrate	8/26/2020	External Agency	<a href="#">View</a>
Calibrate	10/16/2019	External Agency	<a href="#">View</a>
Calibrate	10/8/2018	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
383	26154	26154	Humboldt	UNKNOWN	Calibration Solutions	Calibrate	OS100		View		12	

### Proving Ring (Digital Indicator 001456268)

Action Status	Date	Technician	Certificate
Spare Equipment	10/6/2023		
Calibrate	8/17/2022	External Agency	<a href="#">View</a>
Calibrate	8/27/2021	External Agency	<a href="#">View</a>
Calibrate	8/26/2020	External Agency	<a href="#">View</a>
Calibrate	10/16/2019	External Agency	<a href="#">View</a>
Calibrate	10/8/2018	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
386	26163	26163	ELE	UNKNOWN	Calibration Solutions	Calibrate	OS100		<a href="#">View</a>		12	

**Proving Ring (Dial Indicator 982921403)**

Action Status	Date	Technician	Certificate
Spare Equipment	8/31/2021	McCullough, Donald 0004	
Calibrate	8/26/2020	External Agency	<a href="#">View</a>
Calibrate	10/16/2019	External Agency	<a href="#">View</a>
Calibrate	10/8/2018	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
388	5D-L-03	5D-6-03	Humboldt	UNKNOWN	Calibration Solutions	Calibrate	OS100		<a href="#">View</a>		12	

**Proving Ring (Dial Wykeham Farrance)**

Action Status	Date	Technician	Certificate
Spare Equipment	8/31/2021	McCullough, Donald 0004	
Calibrate	8/26/2020	External Agency	<a href="#">View</a>
Calibrate	10/16/2019	External Agency	<a href="#">View</a>
Calibrate	10/8/2018	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
389	5D-6-98	5D-6-98	Humboldt	UNKNOWN	Calibration Solutions	Calibrate	OS100		<a href="#">View</a>		12	

**Proving Ring (Digital Indicator 021293638)**

Action Status	Date	Technician	Certificate
Spare Equipment	8/31/2021	McCullough, Donald 0004	
Calibrate	8/26/2020	External Agency	<a href="#">View</a>
Calibrate	10/15/2019	External Agency	<a href="#">View</a>
Calibrate	10/8/2018	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
381	8607	8607	Wykeham-Farrance	UNKNOWN	Calibration Solutions	Calibrate	OS100		View		12	

**Proving Ring (Dial Wykeham Farrance)**

Action Status	Date	Technician	Certificate
Spare Equipment	8/31/2021	McCullough, Donald 0004	
Calibrate	8/26/2020	External Agency	<a href="#">View</a>
Calibrate	10/16/2019	External Agency	<a href="#">View</a>
Calibrate	10/8/2018	External Agency	<a href="#">View</a>

**Resilient Modulus**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3669	FL2486	0015-TR25-1	NovoTechnik	047706/A	Geocomp	Calibrate	OS100				12	

**LVDT**

Action Status	Date	Technician	Certificate
Spare Equipment	3/2/2023	McCullough, Donald 0004	
Calibrate	1/24/2023	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3670	FL2486	0015-TR25-2	NovoTechnik	047827/A	Geocomp	Calibrate	OS100				12	

**LVDT**

Action Status	Date	Technician	Certificate
Spare Equipment	3/2/2023	McCullough, Donald 0004	
Calibrate	1/24/2023	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3666	FL2486	1215421	Interface	SML-2000	Geocomp	Calibrate	OS100				12	

**Load Cell - Low Profile**

Action Status	Date	Technician	Certificate
Spare Equipment	3/2/2023	McCullough, Donald 0004	
Calibrate	1/24/2023	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1595	FL2444	19003845	Gefran	GS4201	Calibration Solutions	Calibrate	OS100				12	

Pressure Transducer

Action Status	Date	Technician	Certificate
Spare Equipment	8/25/2023	McCullough, Donald 0004	
Calibrate	8/18/2022	External Agency	<a href="#">View</a>
Calibrate	8/27/2021	External Agency	<a href="#">View</a>
Calibrate	8/26/2020	External Agency	<a href="#">View</a>
In Service	6/22/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1593	FL2444	19090381	Gefran	S02MXL0465	Calibration Solutions	Calibrate	OS100				12	

LVDT

Action Status	Date	Technician	Certificate
Spare Equipment	10/13/2021	McCullough, Donald 0004	
Calibrate	8/26/2020	External Agency	<a href="#">View</a>
In Service	6/22/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1594	FL2444	19090405	Gefran	S02MXL0465	Calibration Solutions	Calibrate	OS100				12	

LVDT

Action Status	Date	Technician	Certificate
Spare Equipment	10/13/2021	McCullough, Donald 0004	
Calibrate	8/26/2020	External Agency	<a href="#">View</a>
In Service	6/22/2020	McCullough, Donald 0004	



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3416	FL2444	20004983	Controls	82-P0324	Calibration Solutions	Standardize	OS100				12	

**LVDT**

Action Status	Date	Technician	Certificate
Spare Equipment	8/25/2023	McCullough, Donald 0004	
Standardize	8/17/2022	External Agency	<a href="#">View</a>
In Service	8/30/2021	McCullough, Donald 0004	
Standardize	8/27/2021	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3415	FL2444	20006502	Controls	82-P0324	Calibration Solutions	Standardize	OS100				12	

**LVDT**

Action Status	Date	Technician	Certificate
Spare Equipment	8/25/2023	McCullough, Donald 0004	
Standardize	8/17/2022	External Agency	<a href="#">View</a>
In Service	8/30/2021	McCullough, Donald 0004	
Standardize	8/27/2021	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3667	FL2486	2006SBALC01010	CAS	SBA-2KLB-I	Geocomp	Calibrate	OS100				12	

**Load Cell - S-beam**

Action Status	Date	Technician	Certificate
Spare Equipment	3/2/2023	McCullough, Donald 0004	
Calibrate	1/24/2023	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1592	FL2444	720456	ontrols (Wykeham-Rarranc	AQUA 25 kN	Calibration Solutions	Calibrate	OS100				12	

**Load Cell**

Action Status	Date	Technician	Certificate
Spare Equipment	8/25/2023	McCullough, Donald 0004	
Calibrate	8/16/2022	External Agency	<a href="#">View</a>
Calibrate	8/27/2021	External Agency	<a href="#">View</a>
Calibrate	8/26/2020	External Agency	<a href="#">View</a>
In Service	6/22/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3664	FL2486	GCC21-0015	Geocomp	11-40051	Geocomp	Calibrate	OS100		<a href="#">View</a>		12	

**CYC - Controller**

Action Status	Date	Technician	Certificate
Spare Equipment	3/2/2023	McCullough, Donald 0004	
Calibrate	1/24/2023	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3665	FL2486	GCC21-0075	Geocomp	2KLBF	Geocomp	Calibrate	OS100				12	

**Loadtrack-II**

Action Status	Date	Technician	Certificate
Spare Equipment	3/2/2023	McCullough, Donald 0004	
Calibrate	1/24/2023	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3668	FL2486	X7988	Honeywell	SPTmV0200P	Geocomp	Calibrate	OS100				12	

**Pressure Transducer**

Action Status	Date	Technician	Certificate
Spare Equipment	3/2/2023	McCullough, Donald 0004	
Calibrate	1/24/2023	External Agency	

## Sieves

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1885	F3	01248511	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status	Date	Technician	Certificate
Spare Equipment	12/7/2020	McCullough, Donald 0004	
Check	11/18/2020	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3330	AG1	01248527	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (4")

Action Status	Date	Technician	Certificate
Spare Equipment	6/24/2021	McCullough, Donald 0004	
In Service	6/22/2021	McCullough, Donald 0004	
Check	11/18/2020	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3605	213520836	213520836	Gilson	V8BH #140	Calibration Solutions	Check	OS100				12	

8" (#140)

Action Status	Date	Technician	Certificate
Spare Equipment	9/15/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3604	213520837	213520837	Gilson	V8BH #140	Calibration Solutions	Check	OS100				12	

8" (#140)

Action Status	Date	Technician	Certificate
Spare Equipment	9/15/2022	McCullough, Donald 0004	

**Specific Gravity**

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3428	10 -boxed	SGC-10	Pyrex	5580	Quality Assurance	Standardize	SOP-109	View			12	

100mL

Action Status	Date	Technician	Certificate
Spare Equipment	10/13/2021	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3429	11 -boxed	SGC-11	Pyrex	5580	Quality Assurance	Standardize	SOP-109	View			12	

100mL

Action Status	Date	Technician	Certificate
Spare Equipment	10/13/2021	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1699	20	SGC-20	Sibata	250 mL	Quality Assurance	Check	SOP-109	View	View		12	

250mL

Action Status	Date	Technician	Certificate
Spare Equipment	10/14/2021	McCullough, Donald 0004	
In Service	12/2/2020	McCullough, Donald 0004	<a href="#">View</a>
Check	12/2/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	12/2/2020	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1698	22	SGC-22	Sibata	250 mL	Quality Assurance	Check	SOP-109	View	View		12	

250mL

Action Status	Date	Technician	Certificate
Spare Equipment	10/14/2021	McCullough, Donald 0004	
Standardize	12/2/2020	Lai, Binh 0057	<a href="#">View</a>
In Service	12/2/2020	McCullough, Donald 0004	<a href="#">View</a>
Check	12/2/2020	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1700	24	SGC-24	Sibata	250 mL	Quality Assurance	Check	SOP-109	View	View		12	

250mL

Action Status	Date	Technician	Certificate
Spare Equipment	10/14/2021	McCullough, Donald 0004	
Standardize	12/2/2020	Lai, Binh 0057	<a href="#">View</a>
Check	12/2/2020	Lai, Binh 0057	<a href="#">View</a>
In Service	12/2/2020	McCullough, Donald 0004	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3426	8 -boxed	SGC-8	Pyrex	5580	Quality Assurance	Standardize	SOP-109	View			12	

100mL

Action Status	Date	Technician	Certificate
Spare Equipment	10/13/2021	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3427	9 -boxed	SGC-9	Pyrex	5580	Quality Assurance	Standardize	SOP-109	View			12	

100mL

Action Status	Date	Technician	Certificate
Spare Equipment	10/13/2021	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1148	SGG-A	SGG-A	Sibata	55	Quality Assurance	Check	SOP-109	View			12	

1000mL

Action Status	Date	Technician	Certificate
Check	12/2/2020	Lai, Binh 0057	<a href="#">View</a>
Standardize	12/2/2020	Lai, Binh 0057	<a href="#">View</a>
Spare Equipment	12/2/2020	McCullough, Donald 0004	<a href="#">View</a>
Standardize	12/17/2019	Lai, Binh 0057	<a href="#">View</a>
Check	12/17/2019	Lai, Binh 0057	<a href="#">View</a>
Check	12/14/2018	Lai, Binh 0057	
Standardize	12/14/2018	Lai, Binh 0057	

## Thermometers

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1200	080086	080086-8	Omega	080086-8	Calibration Solutions	Standardize	OS100		<a href="#">View</a>		12	

Probe#06/Green/Green/8"

Action Status	Date	Technician	Certificate
Spare Equipment	7/28/2022	McCullough, Donald 0004	
Standardize	8/27/2021	External Agency	<a href="#">View</a>
Standardize	8/26/2020	External Agency	<a href="#">View</a>
Standardize	10/17/2019	External Agency	<a href="#">View</a>
Standardize	10/15/2018	External Agency	

Lab Id	Lab Name
96	Central Independent Assurance Unit

## Thermometers

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1215	UNKNOWN	NA1	Cole-Parmer	90090-06	Quality Assurance	Check	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

T-Handle

Action Status	Date	Technician	Certificate
Check	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Standardize	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Check	12/11/2018	Lai, Binh 0057	
Standardize	12/11/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1216	UNKNOWN	NA10	Cole-Parmer	90090-06	Quality Assurance	Check	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

T-Handle

Action Status	Date	Technician	Certificate
Check	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Standardize	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Check	12/11/2018	Lai, Binh 0057	
Standardize	12/11/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1209	UNKNOWN	NA2	Cole-Parmer	90090-06	Quality Assurance	Check	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

**T-Handle**

Action Status	Date	Technician	Certificate
Standardize	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Check	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Standardize	12/11/2018	Lai, Binh 0057	
Check	12/11/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1217	UNKNOWN	NA3	Cole-Parmer	90090-06	Quality Assurance	Check	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

**T-Handle**

Action Status	Date	Technician	Certificate
Check	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Standardize	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Standardize	12/11/2018	Lai, Binh 0057	
Check	12/11/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1218	UNKNOWN	NA4	Cole-Parmer	90090-06	Quality Assurance	Check	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

**T-Handle**

Action Status	Date	Technician	Certificate
Check	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Standardize	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Check	12/11/2018	Lai, Binh 0057	
Standardize	12/11/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1210	UNKNOWN	NA5	Cole-Parmer	90090-06	Quality Assurance	Check	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

**T-Handle**

Action Status	Date	Technician	Certificate
Standardize	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Check	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Check	12/11/2018	Lai, Binh 0057	
Standardize	12/11/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1211	UNKNOWN	NA6	Cole-Parmer	90090-06	Quality Assurance	Check	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

**T-Handle**

Action Status	Date	Technician	Certificate
Check	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Standardize	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Check	12/11/2018	Lai, Binh 0057	
Standardize	12/11/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1212	UNKNOWN	NA7	Cole-Parmer	90090-06	Quality Assurance	Check	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

**T-Handle**

Action Status	Date	Technician	Certificate
Standardize	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Check	12/20/2019	Lai, Binh 0057	<a href="#">View</a>
Standardize	12/11/2018	Lai, Binh 0057	
Check	12/11/2018	Lai, Binh 0057	



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1213	UNKNOWN	NA8	Cole-Parmer	90090-06	Quality Assurance	Check	OS100		View	View	12	

T-Handle

Action Status	Date	Technician	Certificate
Standardize	12/20/2019	Lai, Binh 0057	View
Check	12/20/2019	Lai, Binh 0057	View
Standardize	12/11/2018	Lai, Binh 0057	
Check	12/11/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1214	UNKNOWN	NA9	Cole-Parmer	90090-06	Quality Assurance	Check	OS100		View	View	12	

T-Handle

Action Status	Date	Technician	Certificate
Standardize	12/20/2019	Lai, Binh 0057	View
Check	12/20/2019	Lai, Binh 0057	View
Check	12/11/2018	Lai, Binh 0057	
Standardize	12/11/2018	Lai, Binh 0057	

Lab Id	Lab Name
97	Central Materials Administrative Unit

### Dial or Digital Indicators

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
635	001456268	001456268	Humboldt	BG2500016	Calibration Solutions	Standardize	OS100		View		12	

Digital

Action Status	Date	Technician	Certificate
Spare Equipment	9/21/2023	McCullough, Donald 0004	
Discarded	12/27/2019	Groom, Michael D. 2629	
Standardize	10/8/2018	External Agency	
Calibrate	10/8/2018	External Agency	

### Hardness Measurement (rubber)

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
118	FL1749-1	03865	PTC Instruments	408	oss Precision Measureme	Calibrate	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

**Durometer**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
248	64406-A2	64406-A2	Shore	A-2	oss Precision Measureme	Calibrate	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

**Durometer**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Calibrate	5/1/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1281	FL1749-2	FL1749-2	PTC Instruments	441	oss Precision Measureme	Check	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

**Durometer Constant Load Weight 1kg**

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	

### High Humidity Area

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3466	C05071	C05071	Fluke	5611T		Standardize	<a href="/materials/C97001">/materials/C97001</a>	View			6	

**Probe#XX/Thermister**

Action Status	Date	Technician	Certificate
Spare Equipment	6/2/2021	McCullough, Donald 0004	

## Micro Deval

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
690	3 Refill	3 Refill	Gilson	HMA-922	Quality Assurance	Check	SOP-104	View	View		12	

### Steel Balls

Action Status	Date	Technician	Certificate
Spare Equipment	6/3/2020	McCullough, Donald 0004	
Calibrate	4/5/2019	Lai, Binh 0057	
Check	4/5/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3493	MDC-X-XX	MDC-X-XX	Gilson	HMA-920	Quality Assurance	Check	SOP-104	View			12	

### Container (2 new with balls)

Action Status	Date	Technician	Certificate
Spare Equipment	1/27/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3494	MDSB XX	MDSB XX	Gilson	HMA-922	Quality Assurance	Check	SOP-104	View			12	

### Steel Balls (new box)

Action Status	Date	Technician	Certificate
Spare Equipment	1/27/2022	McCullough, Donald 0004	

## Mixer

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1828	LR0162	31-1617-194	Hobart Corporation	N50	Quality Assurance		SOP-153	View	View			

### 5 Quart Mixer

Action Status	Date	Technician	Certificate
Spare Equipment	6/30/2021	McCullough, Donald 0004	

## Sieves

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1872	W	01061331	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1876	F2	01061353	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1877	F2	01061357	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1878	F3	01061358	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1879	F2	01150203	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#60)

Action Status	Date	Technician	Certificate
Spare Equipment	9/21/2023	McCullough, Donald 0004	
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1884	F3	01248509	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#20)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1886	F2	01248512	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1891	F2	01248523	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1892	W	01248524	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1894	SET-13	01268547	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#4)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      8/4/2020                      McCullough, Donald                      0004  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004  
 Check                      7/16/2019                      Lai, Binh                      0057

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1895	01268551	01268551	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#4)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1899	01268573	01268573	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#80)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1900	01268574	01268574	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#80)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1901	01268578	01268578	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1902	SET-16	01268591	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (3/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1903	SET-13	01409433	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (5/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1913	F3	0227343	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1929	Glass Beads Only	053610006	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#14)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1930	Glass Beads Only	053610007	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#14)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1931	053610008	053610008	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#16)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/13/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1933	06120710	06120710	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#80)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1934	06120711	06120711	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#80)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1935	06139468	06139468	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (1/2")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1937	06139650	06139650	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (3/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1938	06139669	06139669	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#4)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1939	06139670	06139670	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#4)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1940	F1	06172122	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1943	W	06172133	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1944	W	06172134	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1945	W	06172139	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1947	W	06178625	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1948	W	06178628	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1949	06178630	06178630	Gilson	V8CF	Calibration Solutions	Check	OS100				12	

8" (#4)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/13/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1950	9	06178632	Gilson	V8CH #16	Calibration Solutions	Check	OS100		<a href="#">View</a>		12	

8" (#16)

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	2/25/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1951	06178633	06178633	Gilson	V8CF #30	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status	Date	Technician	Certificate
Spare Equipment	7/13/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1952	06178635	06178635	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status	Date	Technician	Certificate
Spare Equipment	7/10/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1954	Set#48	06180159	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	9/2/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1955	W	06180160	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1956	F4	06180162	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1963	07149386	07149386	Gilson	V8CF	Calibration Solutions	Check	OS100				12	

8" (#4)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/13/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1967	071710543	071710543	Gilson	V8CF	Calibration Solutions	Check	OS100				12	

8" (#4)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/13/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1969	07179059	07179059	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/13/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1972	07179464	07179464	Gilson	V8CH #16	Calibration Solutions	Check	OS100				12	

8" (#16)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/13/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1983	08169429	08169429	Gilson	V8CF #30	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status	Date	Technician	Certificate
Spare Equipment	7/13/2020	McCullough, Donald 0004	
Check	7/8/219	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1984	08169431	08169431	Gilson	667924	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	7/10/2020	McCullough, Donald 0004	
Check	7/8/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1986	08169434	08169434	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status	Date	Technician	Certificate
Spare Equipment	7/10/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1987	08169435	08169435	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status	Date	Technician	Certificate
Spare Equipment	7/10/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
1988	W200	08169436	Gilson	V8CH #200	Calibration Solutions	Check	OS100				12	

8" (#200)

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1991	08169439	08169439	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/8")

Action Status	Date	Technician	Certificate
Spare Equipment	7/13/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1993	AG4	092410062	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#12)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/20/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1994	8	092910015	Gilson	V8CH #16	Calibration Solutions	Check	OS100		View		12	

8" (#16)

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Check	2/25/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2001	0979430	0979430	Gilson	V12CH#8	Calibration Solutions	Check	OS100		View		12	

12" (#8)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	7/17/2020	Lai, Binh 0057	View
In Service	7/17/2020	McCullough, Donald 0004	View
Spare Equipment	7/16/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2003	0979438	0979438	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#50)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2007	100SS8F252513	100SS8F252513	Advantech	100SS8F	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2014	10259280	10259280	Gilson	V12CH"025	Calibration Solutions	Check	OS100				12	

12" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      4/30/2021                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2019	10278529	10278529	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#4)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2031	Set#48	10308908	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (5/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/2/2020                      McCullough, Donald                      0004  
 Check                      9/17/2019                      Lai, Binh                      0057                      [View](#)

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2041	1049169	1049169	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#4)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2065	10BB8F010245	10BB8F010245	Gilson	V8CF #10	Calibration Solutions	Check	OS100				12	

8" (#10)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/13/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2066	10BB8F010250	10BB8F010250	Gilson	V8CF #10	Calibration Solutions	Check	OS100				12	

8" (#10)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/13/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2067	SOILS	10BB8F048538	Gilson	V8CF #10	Calibration Solutions	Check	OS100		View		12	

8" (#10)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      12/27/2019                      Groom, Michael D.                      2629

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2154	13126516	13126516	W.S. Tyler	2 in. deep	Calibration Solutions	Check	OS100				12	

8" (9mm)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      12/27/2019                      Groom, Michael D.                      2629



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2155	13126517	13126517	W.S. Tyler	2 in. deep	Calibration Solutions	Check	OS100				12	

8" (10mm)

Action Status Date Technician Certificate  
 Spare Equipment 12/27/2019 Groom, Michael D. 2629

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2266	W	164305	Endecotts	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status Date Technician Certificate  
 Spare Equipment 9/10/2020 McCullough, Donald 0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2302	199308	199308	Endecotts	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#16)

Action Status Date Technician Certificate  
 Spare Equipment 7/13/2020 McCullough, Donald 0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3262	Used	1B used	Gilson	Unknown	Calibration Solutions	Check	OS100				12	

8" (#4)

Action Status Date Technician Certificate  
 Spare Equipment 7/27/2020 McCullough, Donald 0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3484	214324594	214324594	Gilson	V12SF#200B	Calibration Solutions	Check	OS100				12	

12" (#200) (Reinforced)

Action Status Date Technician Certificate  
 Spare Equipment 1/4/2022 McCullough, Donald 0004 [View](#)

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2359	SET-16	237779	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (3/8")

Action Status	Date	Technician	Certificate
Spare Equipment	7/17/2020	McCullough, Donald 0004	
Check	7/17/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2372	PD16-1	278682	Endecotts	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#16)

Action Status	Date	Technician	Certificate
Spare Equipment	7/13/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2373	279004	279004	Endecotts	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#16)

Action Status	Date	Technician	Certificate
Spare Equipment	7/13/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2374	279005	279005	Endecotts	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#16)

Action Status	Date	Technician	Certificate
Spare Equipment	7/13/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3263	Used	2B used	Gilson	Unknown	Calibration Solutions	Check	OS100				12	

8" (#4)

Action Status	Date	Technician	Certificate
Spare Equipment	7/27/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2431	435391	435391	Endecotts	008BAW.425	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2479	Set#48	510917	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#30)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      9/2/2020                      McCullough, Donald                      0004  
 Check                      9/17/2019                      Lai, Binh                      0057                      [View](#)

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2493	5906095	5906095	Endecotts	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#16)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/13/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2591	99091127	99091127	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (3/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2594	99091159	99091159	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (1/2")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2595	99091167	99091167	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	7/17/2020	McCullough, Donald 0004	
Check	7/17/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2598	99121288	99121288	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#8)

Action Status	Date	Technician	Certificate
Spare Equipment	7/16/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2175	AG1	AG1-1.25A	Brainard-Kilman	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (1 1/4")

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/20/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2624	AG1	AG1-2.5A	Brainard-Kilman	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (2 1/2")

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/20/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2625	AG1	AG1-2A	Brainard-Kilman	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (2")

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/20/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2629	AG2	AG2-1.25A	Brainard-Kilman	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (1 1/4")

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/20/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2649	Box	Box-0001	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (1/2")

Action Status	Date	Technician	Certificate
Spare Equipment	7/17/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2650	Box	Box-0002	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	7/17/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2651	Box	Box-0003	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#4)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2653	Box	Box-0005	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#4)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2655	Box	Box-0007	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#20)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2656	Box	Box-0008	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#30)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2657	Box	Box-0009	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#30)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2658	Box	Box-0010	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#40)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2659	Box	Box-0011	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#40)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2660	Box	Box-0012	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#80)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2661	Box	Box-0013	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#80)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2662	Box	Box-0014	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2663	Box	Box-0015	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2664	Box	Box-0016	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2665	Box	Box-0017	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#80)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2666	Box	Box-0018	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#80)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2667	Box	Box-0019	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#80)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2668	Box	Box-0020	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#80)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2669	Box	Box-0021	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#80)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2670	Box	Box-0022	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#80)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2671	Box	Box-0023	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#80)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2672	Box	Box-0024	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#60)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2673	Box	Box-0025	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#60)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2674	Box	Box-0026	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#60)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2675	Box	Box-0027	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2676	Box	Box-0028	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2677	Box	Box-0029	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2678	Box	Box-0030	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2679	Box	Box-0031	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2680	Box	Box-0032	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2681	Box	Box-0033	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2687	Box	Box-0039	Gilson	V8BH#200	Calibration Solutions	Check	OS100				12	

8" (#200)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2688	Box	Box-0040	Gilson	V8BH#200	Calibration Solutions	Check	OS100				12	

8" (#200)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/16/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2689	Box	Box-0041	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2690	Box	Box-0042	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2691	Box	Box-0043	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2692	Box	Box-0044	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2693	Box	Box-0045	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2695	Box	Box-0047	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2696	Box	Box-0048	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2697	Box	Box-0049	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2698	Box	Box-0050	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2699	Box	Box-0051	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2700	Box	Box-0052	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2701	Box	Box-0053	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2702	Box	Box-0054	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2703	Box	Box-0055	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (#6)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/17/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2704	Box	Box-0056	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#25)

Action Status Date Technician Certificate  
 Spare Equipment 7/17/2020 McCullough, Donald 0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2705	Box	Box-0057	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (10000 um)

Action Status Date Technician Certificate  
 Spare Equipment 7/17/2020 McCullough, Donald 0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2706	Box	Box-0059	Unknown	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#325)

Action Status Date Technician Certificate  
 Spare Equipment 7/13/2020 McCullough, Donald 0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2707	Box	Box-0060	W.S. Tyler	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#325)

Action Status Date Technician Certificate  
 Spare Equipment 7/13/2020 McCullough, Donald 0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2708	Box	Box-0061	Humboldt	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#325)

Action Status Date Technician Certificate  
 Spare Equipment 7/13/2020 McCullough, Donald 0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2709	Box	Box-0062	Gilson	667924	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/20/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2711	Box	Box-0064	Gilson	667924	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/20/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2712	Box	Box-0065	Gilson	667924	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/20/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2713	Box	Box-0066	Gilson	667924	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/20/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2714	Box	Box-0067	Gilson	667924	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/20/2020                      McCullough, Donald                      0004



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2715	Box	Box-0068	Gilson	667924	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/20/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2716	Box	Box-0069	Gilson	667924	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/20/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2717	Box	Box-0070	Gilson	667924	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/20/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2718	Box	Box-0071	Gilson	667924	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/20/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2719	Box	Box-0072	Gilson	667924	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/20/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2720	Box	Box-0073	Gilson	667924	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/20/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2721	Box	Box-0074	Gilson	667924	Calibration Solutions	Check	OS100				12	

8" (#50)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/20/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2723	Box	Box-0076	UNKNOWN	008BAW.425	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2724	Box	Box-0077	UNKNOWN	008BAW.425	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2725	Box	Box-0078	UNKNOWN	008BAW.425	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2726	Box	Box-0079	UNKNOWN	008BAW.425	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2727	Box	Box-0080	UNKNOWN	008BAW.425	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2728	Box	Box-0081	UNKNOWN	008BAW.425	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2729	Box	Box-0082	UNKNOWN	008BAW.425	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2730	Box	Box-0083	UNKNOWN	008BAW.425	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2731	Box	Box-0084	UNKNOWN	008BAW.425	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2732	Box	Box-0085	Gilson	V8CF #30	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/13/2020                      McCullough, Donald                      0004  
 Check                      7/8/219                      External Agency

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2733	Box	Box-0086	Gilson	V8CF #30	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/13/2020                      McCullough, Donald                      0004  
 Check                      7/8/219                      External Agency

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2734	Box	Box-0087	Gilson	V8CF #30	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/13/2020                      McCullough, Donald                      0004  
 Check                      7/8/219                      External Agency

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2735	Box	Box-0088	Gilson	V8CF #30	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status	Date	Technician	Certificate
Spare Equipment	7/13/2020	McCullough, Donald 0004	
Check	7/8/219	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2736	Box	Box-0089	Gilson	V8CF #30	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status	Date	Technician	Certificate
Spare Equipment	7/13/2020	McCullough, Donald 0004	
Check	7/8/219	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2737	Box	Box-0090	Gilson	V8CF #30	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status	Date	Technician	Certificate
Spare Equipment	7/13/2020	McCullough, Donald 0004	
Check	7/8/219	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2740	Box	Box-0093	Gilson	V8CH #20	Calibration Solutions	Check	OS100				12	

8" (#20)

Action Status	Date	Technician	Certificate
Spare Equipment	7/10/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2741	Box	Box-0094	Gilson	V8CH #20	Calibration Solutions	Check	OS100				12	

8" (#20)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2742	Box	Box-0095	Gilson	V8CH #20	Calibration Solutions	Check	OS100				12	

8" (#20)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2743	Box	Box-0096	Gilson	V8CH #20	Calibration Solutions	Check	OS100				12	

8" (#20)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2744	Box	Box-0097	Gilson	V8CH #20	Calibration Solutions	Check	OS100				12	

8" (#20)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2745	Box	Box-0098	Gilson	V8CH #20	Calibration Solutions	Check	OS100				12	

8" (#20)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2746	Box	Box-0099	Gilson	V8CH #20	Calibration Solutions	Check	OS100				12	

8" (#20)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/10/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2747	Box	Box-0100	Gilson	V8CF #10	Calibration Solutions	Check	OS100				12	

8" (#10)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      12/27/2019                      Groom, Michael D.                      2629

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2748	Box	Box-0101	Gilson	V8CF #10	Calibration Solutions	Check	OS100				12	

8" (#10)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      12/27/2019                      Groom, Michael D.                      2629

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2749	Box	Box-0102	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#8)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2750	Box	Box-0103	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#8)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2751	Box	Box-0104	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#8)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2752	Box	Box-0105	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#8)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2753	Box	Box-0106	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#8)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2754	Box	Box-0107	UNKNOWN	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#6)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2755	Box	Box-0108	Unknown	Unknown	Calibration Solutions	Check	OS100				12	

8" (#4)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2756	Box	Box-0109	Unknown	Unknown	Calibration Solutions	Check	OS100				12	

8" (#4)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2757	Box	Box-0110	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2758	Box	Box-0111	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2759	Box	Box-0112	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2760	Box	Box-0113	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (1 1/2")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2761	Box	Box-0114	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (5/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2762	Box	Box-0115	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (5/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2763	Box	Box-0116	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (5/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/23/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2764	Box	Box-0117	Gilson	V12CH	Calibration Solutions	Check	OS100				12	

12" (1/4")

Action Status                      Date                      Technician                      Certificate

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2765	Box	Box-0118	Gilson	V12CH	Calibration Solutions	Check	OS100				12	

12" (1/4")

Action Status                      Date                      Technician                      Certificate

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2766	Box	Box-0119	Gilson	V12CH	Calibration Solutions	Check	OS100				12	

12" (1/4")

Action Status                      Date                      Technician                      Certificate

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2768	Box	Box-0121	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (3/8")

Action Status                      Date                      Technician                      Certificate

Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2769	Box	Box-0122	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (3/8")

Action Status                      Date                      Technician                      Certificate

Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2773	Box	Box-0128	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (1/2")

Action Status                      Date                      Technician                      Certificate

Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2774	Box	Box-0129	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

12" (1/2")

Action Status                      Date                      Technician                      Certificate

Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3479	BOX	BOX-132	Gilson	V12CI 3/4"	Calibration Solutions	Check	OS100				12	

12" (3/4")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      1/4/2022                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3481	BOX	BOX-134	Gilson	V12SI #200	Calibration Solutions	Check	OS100				12	

12" (#200)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      1/4/2022                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3482	BOX	BOX-135	Gilson	V12SI #200	Calibration Solutions	Check	OS100				12	

12" (#200)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      1/4/2022                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3280	Used	C3	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#4)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      8/21/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2834	E08484	E08484	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/4")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/13/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2864	F2	F2-12-A	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#12)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2865	F2	F2-16-A	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#16)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2866	F2	F2-20-A	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#20)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2868	F3	F3-100-C	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#100)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2869	F3	F3-12-A	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#12)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2870	F3	F3-16-A	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#16)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2873	F3	F3-60-A	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#60)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2180	G	G 1/2-3	Gilson	TSA100 1/2	Calibration Solutions	Check	OS100				12	

16"X24" (1/2")

Action Status	Date	Technician	Certificate
Spare Equipment	9/2/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2182	G	G 1/4-1	Gilson	TSA100 1/4	Calibration Solutions	Check	OS100				12	

16"X24" (1/4")

Action Status	Date	Technician	Certificate
Spare Equipment	9/2/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2183	G	G 1/4-2	Gilson	TSA100 1/4	Calibration Solutions	Check	OS100				12	

16"X24" (1/4")

Action Status	Date	Technician	Certificate
Spare Equipment	9/2/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2188	G	G 16-1	Gilson	TSA-102#16	Calibration Solutions	Check	OS100				12	

16"X24" (#16)

Action Status	Date	Technician	Certificate
Spare Equipment	9/2/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2190	G	G 20-3	Gilson	TSA102 #20	Calibration Solutions	Check	OS100				12	

16"X24" (#20)

Action Status	Date	Technician	Certificate
Spare Equipment	9/2/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2195	G	G 3/8-1	Gilson	TSA100 3/8	Calibration Solutions	Check	OS100				12	

16"X24" (3/8")

Action Status	Date	Technician	Certificate
Spare Equipment	9/2/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2196	G	G 3/8-2	Gilson	TSA100 3/8	Calibration Solutions	Check	OS100				12	

16"X24" (3/8")

Action Status	Date	Technician	Certificate
Spare Equipment	9/2/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2199	G	G 30	Gilson	TSA-102#30	Calibration Solutions	Check	OS100				12	

16"X24" (#30)

Action Status	Date	Technician	Certificate
Spare Equipment	9/2/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2200	G	G 40-3	Gilson	TSA-100 #4	Calibration Solutions	Check	OS100				12	

16"X24" (#40)

Action Status	Date	Technician	Certificate
Spare Equipment	9/2/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2201	G	G 4-3	Gilson	TSA-100 #4	Calibration Solutions	Check	OS100				12	

16"X24" (#4)

Action Status	Date	Technician	Certificate
Spare Equipment	9/2/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2205	G	G 5/8-2	Gilson	TSA100 5/8	Calibration Solutions	Check	OS100				12	

16"X24" (5/8")

Action Status	Date	Technician	Certificate
Spare Equipment	9/2/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
2206	G	G 50-2	Gilson	TSA102 #50	Calibration Solutions	Check	OS100				12	

16"X24" (#50)

Action Status	Date	Technician	Certificate
Spare Equipment	9/2/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3260	Used	P2B1	Dual	Unknown	Calibration Solutions	Check	OS100				12	

8" (#4)

Action Status	Date	Technician	Certificate
Spare Equipment	7/27/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3070	PR	PR-1/4-1A	Soiltest	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (1/4")

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3071	PR1	PR1-1-1A	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (1")

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3074	PR	PR-2.5-1A	Humboldt	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (2 1/2")

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3080	PR	PR-3/8-2A	Melton	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/8")

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3083	PR	PR-4-2A	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#4)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3084	PR	PR-8-1A	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#8)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3086	PS1	PS1-10A	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#10)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3088	PS2	PS2-40B	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3089	PS3	PS3-10A	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#10)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3090	PS3	PS3-40A	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3092	PS4	PS4-40A	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/7/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3100	R1	R1-40-2-A	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald 0004	
Check	11/20/2019	Lai, Binh 0057	
Check	11/21/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3239	Used	Used-0001	SoilTest	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#40)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3240	Used	Used-0002	W.S. Tyler	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#16)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3242	Used	Used-0004	Advantech	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3243	Used	Used-0005	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3244	Used	Used-0006	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3245	Used	Used-0007	Humboldt	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3246	Used	Used-0008	Humboldt	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3247	Used	Used-0009	SoilTest	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3248	Used	Used-0010	SoilTest	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#30)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3249	Used	Used-0011	Advantech	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#16)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3250	Used	Used-0012	SoilTest	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#20)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3251	Used	Used-0013	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#10)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3252	Used	Used-0014	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#10)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3253	Used	Used-0015	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#8)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3254	Used	Used-0016	Advantech	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#8)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3255	Used	Used-0017	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#8)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3256	Used	Used-0018	ATM	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#8)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3257	Used	Used-0019	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#6)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3258	Used	Used-0020	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#6)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3259	Used	Used-0021	Melton	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (5/16")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004



Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3261	Used	Used-0023	Humboldt	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (1/4")

Action Status Date Technician Certificate  
 Spare Equipment 7/27/2020 McCullough, Donald 0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3264	Used	Used-0026	Dual	Unknown	Calibration Solutions	Check	OS100				12	

8" (#4)

Action Status Date Technician Certificate  
 Spare Equipment 7/27/2020 McCullough, Donald 0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3267	Used	Used-0030	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (1/2")

Action Status Date Technician Certificate  
 Spare Equipment 7/27/2020 McCullough, Donald 0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3268	Used	Used-0031	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (1/2")

Action Status Date Technician Certificate  
 Spare Equipment 7/27/2020 McCullough, Donald 0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3269	Used	Used-0032	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/8")

Action Status Date Technician Certificate  
 Spare Equipment 7/27/2020 McCullough, Donald 0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3270	Used	Used-0033	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3271	Used	Used-0034	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3272	Used	Used-0035	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3273	Used	Used-0036	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (5/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3274	Used	Used-0037	SoilTet	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/4")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3275	Used	Used-0038	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/4")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3278	Used	Used-0041	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (1 1/2")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      7/27/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3279	Used	Used-0043	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#8)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      8/21/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3281	Used	Used-0045	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (3/8")

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      8/21/2020                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3450	Used	Used-0046	W.S. Tyler	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#20)

Action Status                      Date                      Technician                      Certificate  
 Spare Equipment                      10/18/2021                      McCullough, Donald                      0004

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3284	W	W270-19A	Gilson	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#270)

Action Status	Date	Technician	Certificate
Spare Equipment	9/10/2020	McCullough, Donald	0004

### Tamping Tools

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1186	STR-34	STR 34	Humboldt	H-2905.1	Quality Assurance	Check	SOP-149	View	View		12	

Rod - small

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D.	2629

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
553	STR-3	STR-3	Humboldt	H-2905.1	Quality Assurance	Check	SOP-149	View	View		12	

Rod - small

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D.	2629
Check	4/8/2019	Lai, Binh	0057

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
549	TR-7	TR-7	Gilson	HM-48A	Quality Assurance	Check	SOP-149	View	View	View	12	

Rod - large

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D.	2629
Check	4/8/2019	Lai, Binh	0057

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
547	TR-new	TR-new	Humboldt	H-3651	Quality Assurance	Check	SOP-149	View	View		12	

Rod - large

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	

## Thermometers

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3348	F97005647 LOT#89	12-09-11	Barnant	IMS SE	Calibration Solutions	Standardize	OS100		View		12	

Probe??/12"

Action Status	Date	Technician	Certificate
Spare Equipment	9/1/2021	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1204	486036	486036	EUTECH	Type K	Calibration Solutions	Standardize	OS100		View	View	12	

Digital Display/Digi-Sense

Action Status	Date	Technician	Certificate
Spare Equipment	12/1/2020	Groom, Michael D. 2629	
Standardize	10/14/2019	External Agency	View
Standardize	6/6/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
4	486036	486036-26	EUTECH	Type K	Calibration Solutions	Standardize	OS100		View		12	

Probe#26/Thermocouple

Action Status	Date	Technician	Certificate
Spare Equipment	12/1/2020	Groom, Michael D. 2629	
Standardize	10/14/2019	External Agency	View

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
13	FL2296-80093	80093	Fluke	5616-12	Calibration Solutions	Standardize	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

Probe#80093/12"

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
14	FL2296	A86053	Fluke	1521	Calibration Solutions	Standardize	OS100		<a href="#">View</a>	<a href="#">View</a>	12	

Digital Display

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Standardize	9/12/2019	External Agency	
Calibrate	9/12/2019	External Agency	
Standardize	10/29/2018	External Agency	
Calibrate	10/29/2018	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1208	C02003355-2	C02003355-2	Cole-Parmer	08516-96	Calibration Solutions	Standardize	OS100				12	

Probe Two Braided Probe

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3347	F97005647	F97005647	Barnant	600-2810	Calibration Solutions	Standardize	OS100				12	

Digital Display

Action Status	Date	Technician	Certificate
Spare Equipment	9/1/2021	McCullough, Donald 0004	

## Thermometers - High Humidity Area

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1364	LAT0261	C07411	Fluke	1620A-S	Quality Assurance	Check	SOP-106	View	View		6	

### Display Module/Thermo-Hygrometers

Action Status	Date	Technician	Certificate
Spare Equipment	9/24/2020	Groom, Michael D. 2629	
Equipment Repurposed	7/15/2020	McCullough, Donald 0004	
Check	7/2/2020	External Agency	<a href="#">View</a>

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1365	LAT0261-C07837	C07837	Fluke	2626-S	Quality Assurance	Check	SOP-106	View			6	

### Sensor/Thermo-Hygrometers

Action Status	Date	Technician	Certificate
Spare Equipment	7/15/2020	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1363	LAT0261-C07837	C07880	Fluke	2626-S	Quality Assurance	Check	SOP-106	View			6	

### Sensor/Thermo-Hygrometers

Action Status	Date	Technician	Certificate
Spare Equipment	7/15/2020	McCullough, Donald 0004	

## Timing Devices

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1247	122582361	122582361	Control Company	5025	Quality Assurance	Standardize	SOP-114	View	View		12	

### Timer

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Standardize	3/12/2019	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
325	122582397	122582397	Control Company	5025	Quality Assurance	Standardize	SOP-114	View	View		12	

Timer

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Standardize	3/12/2019	Lai, Binh 0057	

### Variable Length Measurement

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
1742	DC03 Sylvac	DC03	Fowler	Ultra-Cal	Quality Assurance	Check	SOP-101	View	View	View	12	

Calipers 8"

Action Status	Date	Technician	Certificate
Spare Equipment	1/6/2021	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
58	S0480044	S0480044	Starrett	No.123	Quality Assurance	Standardize	SOP-101	View	View	View	12	

Calipers 14" (Vernier)

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Calibrate	10/8/2018	Lai, Binh 0057	
Standardize	10/8/2018	Lai, Binh 0057	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
3709	S0480055	S0480055	Scherr Tumico	No.16 0197	Quality Assurance	Standardize	SOP-101	View			12	

Calipers 16" (Vernier)

Action Status	Date	Technician	Certificate
Spare Equipment	8/30/2023	McCullough, Donald 0004	



## Weights

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3575	PS0391	162950	Troemner	1mg-2kg	OK Bureau of Standards	Calibrate	OS100		<a href="#">View</a>		12	

### Precision Weight Set

Action Status	Date	Technician	Certificate
Spare Equipment	7/22/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
3576	PS0392	162951	Troemner	1mg-2kg	OK Bureau of Standards	Calibrate	OS100		<a href="#">View</a>		12	

### Precision Weight Set

Action Status	Date	Technician	Certificate
Spare Equipment	7/22/2022	McCullough, Donald 0004	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
763	WS0001	WS0001	Avoirdupois	50-lb	OK Bureau of Standards	Calibrate	OS100		<a href="#">View</a>		12	

### Precision Weight Set

Action Status	Date	Technician	Certificate
Calibrate	4/24/2023	McCullough, Donald 0004	<a href="#">View</a>
Calibrate	6/2/2022	McCullough, Donald 0004	<a href="#">View</a>
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Calibrate	8/19/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	Calib. Due Dt.
764	WS0002	WS0002	Avoirdupois	50-lb	OK Bureau of Standards	Calibrate	OS100		<a href="#">View</a>		12	

### Precision Weight Set

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Calibrate	8/19/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
765	WS0003	WS0003	Avoirdupois	50-lb	OK Bureau of Standards	Calibrate	OS100		View		12	

Precision Weight Set

Action Status	Date	Technician	Certificate
Calibrate	4/24/2023	McCullough, Donald 0004	View
Calibrate	6/2/2022	McCullough, Donald 0004	View
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Calibrate	8/19/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
767	WS0005	WS0005	Avoirdupois	50lb-1/32z	OK Bureau of Standards	Calibrate	OS100		View		12	

Precision Weight Set

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Calibrate	8/19/2019	External Agency	

Spare Equipment											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
768	WS0006	WS0006	Avoirdupois	100g-100mg	OK Bureau of Standards	Calibrate	OS100		View		12	

Precision Weight Set

Action Status	Date	Technician	Certificate
Spare Equipment	12/27/2019	Groom, Michael D. 2629	
Calibrate	8/19/2019	External Agency	