

Lab Equipment Calibration
(Repurposed Equipment)

Frequency (Mnths.)	Count of Equip.
3	1
12	5

Total Equipment: 6

Lab Id	Lab Name
92	Central Chemical Lab

Sieves

Equipment Repurposed											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2049	2	10519477	Gilson	V12SF #200	Calibration Solutions	Check	OS100				12	

12" (#200)

Action Status	Date	Technician	Certificate
Equipment Repurposed	7/16/2020	McCullough, Donald	0004

Equipment Repurposed											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2299	V6FS-50	194922286	Gilson	V6FS #200	Calibration Solutions	Check	OS100				12	

6" (#200) (drain cover)

Action Status	Date	Technician	Certificate
Equipment Repurposed	11/8/2023	McCullough, Donald	0004
Check	8/29/2023	External Agency	View
Check	8/18/2022	External Agency	View
Check	8/30/2021	External Agency	View
Check	4/15/2021	Lai, Binh 0057	View
Check	7/20/2020	Lai, Binh 0057	View
Check	4/18/2020	Lai, Binh 0057	
Check	7/8/2019	Lai, Binh 0057	View

Equipment Repurposed											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
2780	C16-3	C16-3	Dual	UNKNOWN	Calibration Solutions	Check	OS100				12	

8" (#16)

Action Status	Date	Technician	Certificate
Check	4/16/2021	Lai, Binh 0057	View
Check	7/20/2020	Lai, Binh 0057	View
In Service	7/6/2020	McCullough, Donald 0004	
Check	4/18/2020	Lai, Binh 0057	

Lab Id	Lab Name
93	Central Bituminous Mixture Lab

Corelok Vacuum

Equipment Repurposed											Freq.	Calib. Due Dt.
Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	(Months)	
618	LVP0082	1005	InstroTek	I-225	Quality Assurance	Check	SOP-118	View	View	View	3	

Corelok Vacuum System

Action Status	Date	Technician	Certificate
Equipment Repurposed	12/14/2020	McCullough, Donald 0004	
Check	9/10/2020	Lai, Binh 0057	View
Check	6/15/2020	Lai, Binh 0057	View
Check	3/18/2020	Lai, Binh 0057	View
Check	12/9/2019	Lai, Binh 0057	
Check	9/16/2019	Lai, Binh 0057	View
Check	6/6/2019	Lai, Binh 0057	View
Check	3/15/2019	Lai, Binh 0057	View

Lab Id Lab Name
 97 Central Materials Administrative Unit

Sieves

Equipment Repurposed

Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	Freq. (Months)	Calib. Due Dt.
2204	G	G 4-9	Gilson	TSA-100 #4	Quality Assurance	Check	SOP-183	View			12	

16"X24" (#4)

Action Status	Date	Technician	Certificate
Out of Service for Repair	2/4/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	View

Equipment Repurposed

Id Nbr.	ODOT Equip. Id	Serial Number	Manufacturer Name	Model Number	Calib. Source	Calib. Method	Verif. Procedure	Calib. Form	ODOT Form 72b	Equip. Manual	Freq. (Months)	Calib. Due Dt.
2207	G	G 8-1	Gilson	TSA-101 #8	Quality Assurance	Check	SOP-183	View			12	

16"X24" (#8)

Action Status	Date	Technician	Certificate
Out of Service for Repair	7/10/2020	McCullough, Donald 0004	
Check	9/17/2019	Lai, Binh 0057	View
Check	9/6/2018	Lai, Binh 0057	View