

IA Asphalt Plant Inspections and Scale Certifications

Plant Name: **Cummins Const Co #2713 (Coleman, OK)**

Plant ID: **m00556-11**

<u>Eval. Date</u>	<u>Evaluator</u>	<u>Sample ID</u>	<u>Insp. Rslts.</u>	<u>Plant Inspection</u>	<u>Scale Certification</u>	<u>Scale Cert. Dt.</u>
3/20/2024	Gaxiola, Anthony J.	9636282403200900	Satisfactory	View	View	03/13/2024
9/21/2023	Baggett, Michael J.	9620782309211545	Satisfactory		View	09/20/2023
3/23/2023	Baggett, Michael J.	9620782303231330	Satisfactory	View	View	03/21/2023
9/21/2022	Baggett, Michael J.	9620782209210800	Satisfactory		View	09/20/2022
4/13/2022	Baggett, Michael J.	9620782204131100	Satisfactory	View	View	03/31/2022
10/14/2021	Baggett, Michael J.	9620782110141130	Satisfactory		View	10/12/2021
5/12/2021	Baggett, Michael J.	9620782105121030	Satisfactory	View	View	04/28/2021
11/4/2020	Baggett, Michael J.	9620782011040800	Satisfactory		View	11/03/2020
5/20/2020	Baggett, Michael J.	9620782005200930	Satisfactory	View	View	05/12/2020
5/13/2020	Baggett, Michael J.	9620782005130930	Satisfactory		View	05/12/2020
1/23/2020	Baggett, Michael J.	9620782001230800	Satisfactory		View	11/18/2019
10/31/2019	Baggett, Michael J.	9620781910311530	Satisfactory		View	08/13/2019
5/2/2019	Baggett, Michael J.	9620781905020830	Satisfactory	View	View	04/25/2019
11/28/2018	Baggett, Michael J.	9620781811280900	Satisfactory		View	11/27/2018
5/30/2018	Baggett, Michael J.	9620781805300900	Satisfactory	View		