

IA Asphalt Plant Inspections and Scale Certifications

Plant Name: **Jenkins #1 (Lawton, OK) - 300TPH**

Plant ID: **m00561-01**

<u>Eval. Date</u>	<u>Evaluator</u>	<u>Sample ID</u>	<u>Insp. Rslts.</u>	<u>Plant Inspection</u>	<u>Scale Certification</u>	<u>Scale Cert. Dt.</u>
12/18/2023	Macon, Deanne	9622412312180930	Satisfactory		View	12/14/2023
9/7/2023	Macon, Deanne	9622412309071115	Satisfactory	View	View	07/05/2023
7/5/2023	Macon, Deanne	9622412307051330	Satisfactory		View	07/05/2023
1/6/2023	Macon, Deanne	9622412301061400	Satisfactory		View	01/06/2023
9/7/2022	Macon, Deanne	9622412209071420	Satisfactory	View	View	07/12/2022
7/12/2022	Macon, Deanne	9622412207120900	Satisfactory		View	07/12/2022
6/7/2022	Macon, Deanne	9622412206071100	Satisfactory		View	01/13/2022
12/7/2021	Macon, Deanne	9622412201101330	Satisfactory		View	12/07/2021
9/20/2021	Macon, Deanne	9622412109201325	Satisfactory	View	View	07/15/2021
7/15/2021	Macon, Deanne	9622412107151220	Satisfactory		View	07/15/2021
5/12/2021	Macon, Deanne	9622412105121345	Satisfactory		View	02/03/2021
1/19/2021	Macon, Deanne	9622412101130800	Satisfactory		View	11/16/2020
9/22/2020	Macon, Deanne	9622412009220930	Satisfactory	View	View	07/17/2020
7/17/2020	Macon, Deanne	9622412007171500	Satisfactory		View	07/17/2020
1/23/2020	Macon, Deanne	9622412001230930	Satisfactory		View	01/17/2020
9/24/2019	Macon, Deanne	9622411909241000	Satisfactory	View	View	08/01/2019
8/6/2019	Steinhouse, Kelly D.	9620811908060950	Satisfactory		View	08/01/2019
2/4/2019	Macon, Deanne	9622411902041230	Satisfactory		View	02/04/2019
10/3/2018	Macon, Deanne	9622411810031230	Satisfactory	View	View	08/07/2018
8/13/2018	Macon, Deanne	9622411808130918	Satisfactory		View	08/07/2018
2/8/2018	Macon, Deanne	9622411802080930	Satisfactory		View	02/08/2018