

IA Asphalt Plant Inspections and Scale Certifications

Plant Name: **Pav. Matls. of Southern OK. #2791- 400 TPH**

Plant ID: **m00697-01**

<u>Eval. Date</u>	<u>Evaluator</u>	<u>Sample ID</u>	<u>Insp. Rslts.</u>	<u>Plant Inspection</u>	<u>Scale Certification</u>	<u>Scale Cert. Dt.</u>
1/16/2025	Macon, Deanne	9622412501161000	Satisfactory		View	01/15/2025
8/28/2024	Macon, Deanne	9622412408281130	Satisfactory	View	View	07/11/2024
7/11/2024	Macon, Deanne	9622412407111330	Satisfactory		View	07/11/2024
1/9/2024	Macon, Deanne	9622412401090900	Satisfactory		View	01/03/2024
9/13/2023	Macon, Deanne	9622412309131130	Satisfactory	View	View	07/18/2023
7/25/2023	Macon, Deanne	9622412307251500	Satisfactory		View	07/18/2023
1/20/2023	Macon, Deanne	9622412301200930	Satisfactory		View	01/19/2023
9/20/2022	Macon, Deanne	9622412209200900	Satisfactory	View	View	07/22/2022
6/22/2022	Macon, Deanne	9622412206221430	Satisfactory		View	06/20/2022
12/14/2021	Macon, Deanne	9622412112141000	Satisfactory		View	12/14/2021
9/22/2021	Macon, Deanne	9622412109220930	Satisfactory	View	View	06/23/2021
7/1/2021	Macon, Deanne	9622412107011340	Satisfactory		View	06/23/2021
1/5/2021	Macon, Deanne	9622412101050930	Satisfactory		View	01/05/2021
9/23/2020	Macon, Deanne	9622412009230900	Satisfactory	View	View	07/03/2020
7/3/2020	Macon, Deanne	9622412007031000	Satisfactory		View	07/03/2020
3/4/2020	Macon, Deanne	9622412003040900	Satisfactory		View	01/07/2020
9/24/2019	Macon, Deanne	9622411909241400	Satisfactory	View	View	09/05/2019
2/8/2019	Macon, Deanne	9622411902081300	Satisfactory		View	02/08/2019
10/2/2018	Macon, Deanne	9622411810021420	Satisfactory	View	View	08/14/2018
8/15/2018	Macon, Deanne	9622411808151520	Satisfactory		View	08/14/2018
6/18/2018	Macon, Deanne	9622411806181000	Satisfactory		View	02/13/2018