

IA Asphalt Plant Inspections and Scale Certifications

Plant Name: **Seal Masters Inc. (Davis, OK) - 300 TPH**

Plant ID: **m00790-02**

<u>Eval. Date</u>	<u>Evaluator</u>	<u>Sample ID</u>	<u>Insp. Rslts.</u>	<u>Plant Inspection</u>	<u>Scale Certification</u>	<u>Scale Cert. Dt.</u>
12/4/2023	Macon, Deanne	9622412312041400	Satisfactory		View	12/04/2023
6/8/2023	Macon, Deanne	9622412306071130	Satisfactory		View	06/07/2023
4/28/2023	Macon, Deanne	9622412304280900	Satisfactory	View	View	12/14/2022
12/14/2022	Macon, Deanne	9622412212141600	Satisfactory		View	12/14/2022
6/23/2022	Macon, Deanne	9622412206231430	Satisfactory		View	06/21/2022
5/3/2022	Macon, Deanne	9622412205031330	Satisfactory	View	View	12/14/2021
12/20/2021	Macon, Deanne	9622412112200900	Satisfactory		View	12/14/2021
6/24/2021	Macon, Deanne	9622412106241400	Satisfactory		View	06/24/2021
5/5/2021	Macon, Deanne	9622412105050730	Satisfactory	View	View	01/06/2021
1/6/2021	Macon, Deanne	9622412101061400	Satisfactory		View	01/06/2021
7/2/2020	Macon, Deanne	9622412007020930	Satisfactory		View	07/02/2020
6/11/2020	Macon, Deanne	9622412006111101	Satisfactory	View	View	01/06/2020
1/23/2020	Macon, Deanne	9622412001230900	Satisfactory		View	01/06/2020
10/25/2019	Macon, Deanne	9622411910251430	Satisfactory		View	08/06/2019
7/17/2019	Barris, Caleb B.	9625741907171100	Satisfactory	View	View	05/14/2019
6/25/2019	Barris, Caleb B.	9625741906251330	Unsatisfactory	View	View	05/14/2019