

[ODOT IA Evaluated Technicians](#)

Technician Evaluation Details

Tech. Name: **Castillo, Casey** Tech ID: **ccastill** Cert. No.: **3477**

Aggregates (Controlled)						
<u>Eval. Date</u>	<u>Evaluator</u>	<u>Eval. Level</u>	<u>Sample ID</u>	<u>Proc.</u>	<u>Equip.</u>	<u>Evaluation</u>
6/7/2016	Macon, Deanne	Fully Certified	9622411606071330	Pass	Pass	View
6/1/2015	Steinhouse, Kelly D.	Fully Certified	9620811506011124	Pass	Pass	View
4/29/2014	Smith, David M.	Fully Certified	9620461404290837	Pass	Pass	View

Asphalt (Controlled)						
<u>Eval. Date</u>	<u>Evaluator</u>	<u>Eval. Level</u>	<u>Sample ID</u>	<u>Proc.</u>	<u>Equip.</u>	<u>Evaluation</u>
6/6/2016	Macon, Deanne	Fully Certified	9622411606061100	Pass	Pass	View
6/1/2015	Steinhouse, Kelly D.	Fully Certified	9620811506011329	Pass	Pass	View
4/28/2014	Smith, David M.	Fully Certified	9620461404281351	Pass	Pass	View

Concrete (Controlled)						
<u>Eval. Date</u>	<u>Evaluator</u>	<u>Eval. Level</u>	<u>Sample ID</u>	<u>Proc.</u>	<u>Equip.</u>	<u>Evaluation</u>
6/8/2016	Macon, Deanne	Fully Certified	9622411606080930	Pass	Pass	View
4/9/2015	Steinhouse, Kelly D.	Fully Certified	9620811504091115	Pass	Pass	View
4/29/2014	Smith, David M.	Fully Certified	9620461404291533	Pass	Pass	View

Soils (Controlled)						
<u>Eval. Date</u>	<u>Evaluator</u>	<u>Eval. Level</u>	<u>Sample ID</u>	<u>Proc.</u>	<u>Equip.</u>	<u>Evaluation</u>
8/24/2015	Riley, Luther Roy	Fully Certified	9625951508240737	Pass	Pass	View