

[ODOT IA Evaluated Technicians](#)

**Technician Evaluation Details**

Tech. Name: **Lopez-Roman, Jose**      Tech ID: **jlopez**      Cert. No.: **3971**

**Asphalt (Controlled)**

<u>Eval. Date</u>	<u>Evaluator</u>	<u>Eval. Level</u>	<u>Sample ID</u>	<u>Proc.</u>	<u>Equip.</u>	<u>Evaluation</u>
4/28/2022	Barris, Caleb B.	Materials Sampler	9625742204281000	Pass	Pass	<a href="#">View</a>

**Concrete (Controlled)**

<u>Eval. Date</u>	<u>Evaluator</u>	<u>Eval. Level</u>	<u>Sample ID</u>	<u>Proc.</u>	<u>Equip.</u>	<u>Evaluation</u>
2/15/2022	Barris, Caleb B.	Materials Sampler	9625742202151030	Pass	Pass	<a href="#">View</a>
11/10/2020	Barris, Caleb B.	Materials Sampler	9625742011101100	Pass	Pass	<a href="#">View</a>
7/23/2019	Baggett, Michael J.	Materials Sampler	9620781907230830	Pass	Pass	<a href="#">View</a>

**Soils (Controlled)**

<u>Eval. Date</u>	<u>Evaluator</u>	<u>Eval. Level</u>	<u>Sample ID</u>	<u>Proc.</u>	<u>Equip.</u>	<u>Evaluation</u>
10/20/2022	Macon, Deanne	Materials Sampler	9622412210202800	Pass	Pass	<a href="#">View</a>
7/17/2020	Macon, Deanne	Materials Sampler	9622412007170925	Pass	Pass	<a href="#">View</a>
4/26/2019	Weber, Wendell Eugene Jr. (Gene)	Materials Sampler	9630711904260940	Pass	Pass	<a href="#">View</a>