

[ODOT IA Evaluated Technicians](#)

Technician Evaluation Details

Tech. Name: **Roberts, Cole** Tech ID: **crober01** Cert. No.: **4276**

Aggregates (Controlled)

<u>Eval. Date</u>	<u>Evaluator</u>	<u>Eval. Level</u>	<u>Sample ID</u>	<u>Proc.</u>	<u>Equip.</u>	<u>Evaluation</u>
12/11/2023	Gaxiola, Anthony J.	Materials Sampler	9636282312110830	Pass	Pass	View
8/8/2022	Macon, Deanne	Materials Sampler	9622412208081510	Pass	Pass	View

Asphalt (Controlled)

<u>Eval. Date</u>	<u>Evaluator</u>	<u>Eval. Level</u>	<u>Sample ID</u>	<u>Proc.</u>	<u>Equip.</u>	<u>Evaluation</u>
12/11/2023	Gaxiola, Anthony J.	Materials Sampler	9636282312110930	Pass	Pass	View
8/8/2022	Macon, Deanne	Materials Sampler	9622412208081530	Pass	Pass	View

Concrete (Controlled)

<u>Eval. Date</u>	<u>Evaluator</u>	<u>Eval. Level</u>	<u>Sample ID</u>	<u>Proc.</u>	<u>Equip.</u>	<u>Evaluation</u>
12/11/2023	Gaxiola, Anthony J.	Materials Sampler	9636282312111030	Pass	Pass	View
8/8/2022	Macon, Deanne	Materials Sampler	9622412208081600	Pass	Pass	View

Soils (Controlled)

<u>Eval. Date</u>	<u>Evaluator</u>	<u>Eval. Level</u>	<u>Sample ID</u>	<u>Proc.</u>	<u>Equip.</u>	<u>Evaluation</u>
8/8/2022	Macon, Deanne	Materials Sampler	9622412208081545	Pass	Pass	View